

AD-A105 768

BAKER (MICHAEL) JR INC BEAVER PA  
NATIONAL DAM SAFETY PROGRAM. WOODWARD DAM (INVENTORY NUMBER NY --ETC(U)  
JUN 81 G KESTER


F/G 13/13

DACW51-81-C-0010

NL

UNCLASSIFIED

1 of 2  
AD-A105 768  
28-58



LOWER HUDSON RIVER BASIN

4


**WOODWARD DAM**

LEVEL II

ORANGE COUNTY, NEW YORK  
INVENTORY NO. 507

AD A105768

**PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM**



APPROVED FOR PUBLIC RELEASE;  
DISTRIBUTION UNLIMITED

DTIC  
SELECTED  
JUL 1 1981

D

NEW YORK DISTRICT CORPS OF ENGINEERS

JUNE 1981

70 19

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
	AD-A420576	
4. TITLE (and Subtitle) Phase I Inspection Report Woodward Dam Lower Hudson River Basin, Orange County, NY Inventory 507		5. TYPE OF REPORT & PERIOD COVERED Phase I Inspection Report National Dam Safety Program
7. AUTHOR(s) GRANVILLE KESTER, JR.		6. PERFORMING ORG. REPORT NUMBER
		8. CONTRACT OR GRANT NUMBER(s) (15) DACW51-81-C-0010
9. PERFORMING ORGANIZATION NAME AND ADDRESS Michael Baker, Jr. Inc. 4301 Dutch Ridge Road Box 280 Beaver, PA 15009		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS (12) 557
11. CONTROLLING OFFICE NAME AND ADDRESS Department of the Army 26 Federal Plaza New York District, CofE New York, New York 10287		12. REPORT DATE (11) 30 June 1981
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) Department of the Army 26 Federal Plaza New York District, CofE New York, NY 10287		13. NUMBER OF PAGES
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report)  Approved for public release; Distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)  (6) National Dam Safety Program. Woodward Dam (Inventory Number NY 507), Lower Hudson River Basin, Orange County, New York. Phase I Inspection Report.		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety Woodward Dam National Dam Safety Program Orange County Visual Inspection Lower Hudson River Basin Hydrology, Structural Stability		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number)  This report provides information and analysis on the physical condition of the dam as of the report date. Information and analysis are based on visual inspection of the dam by the performing organization.  Examination of available documents and a visual inspection of the dam and appurtenant structures did not reveal conditions which constitute an immediate hazard to human life or property.		

Using the Corps of Engineers' screening criteria, it has been determined that the dam would be overtopped for all storms exceeding approximately 60 percent of the Probable Maximum Flood (PMF). Therefore, the spillway is adjudged "inadequate."

No signs of instability were noted in the embankment; therefore, no stability analysis will be required.

Current inspection and maintenance procedures by the owner are adequate but need to be documented. Monitoring of the reservoir levels should be expanded to include readings during peak flow periods.

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A	

DTIC  
ELECTE  
S OCT 19 1981 D

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM  
WOODWARD DAM  
I.D. No. NY 507  
DEC DAM No. 179A-562 LOWER HUDSON RIVER BASIN  
ORANGE COUNTY, NEW YORK

TABLE OF CONTENTS

	<u>PAGE NO.</u>
- ASSESSMENT	-
- OVERVIEW PHOTOGRAPH	-
1 PROJECT INFORMATION	1
1.1 GENERAL	1
1.2 DESCRIPTION OF PROJECT	1
1.3 PERTINENT DATA	3
2 ENGINEERING DATA	5
2.1 GEOLOGY	5
2.2 SUBSURFACE INVESTIGATION	5
2.3 DAM AND APPURTENANT STRUCTURES	6
2.4 CONSTRUCTION RECORDS	6
2.5 OPERATION RECORDS	6
2.6 EVALUATION OF DATA	7
3 VISUAL INSPECTION	9
3.1 FINDINGS	9
3.2 EVALUATION	11
4 OPERATION AND MAINTENANCE PROCEDURES	13
4.1 PROCEDURES	13
4.2 MAINTENANCE OF THE DAM	13
4.3 WARNING SYSTEM	13
4.4 EVALUATION	13
5 HYDRAULIC/HYDROLOGIC	15
5.1 DRAINAGE AREA CHARACTERISTICS	15
5.2 ANALYSIS CRITERIA	15
5.3 SPILLWAY CAPACITY	15
5.4 RESERVOIR CAPACITY	16
5.5 FLOODS OF RECORD	16
5.6 OVERTOPPING POTENTIAL	16
5.7 RESERVOIR EMPTYING POTENTIAL	16
5.8 EVALUATION	16

	<u>PAGE NO.</u>
6     STRUCTURAL STABILITY	17
6.1   EVALUATION OF EMBANKMENT STABILITY	17
6.2   STABILITY ANALYSIS	17
6.3   SEISMIC STABILITY	18
7     ASSESSMENT/RECOMMENDATIONS	19
7.1   ASSESSMENT	19
7.2   RECOMMENDED MEASURES	19

#### APPENDIX

- A.    PHOTOGRAPHS
- B.    VISUAL INSPECTION CHECKLIST
- C.    HYDROLOGIC/HYDRAULIC DATA AND COMPUTATIONS
- D.    REFERENCES
- E.    DRAWINGS
- F.    BACKGROUND DOCUMENTS

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Woodward Dam (I.D. NY 507)  
State: New York  
County: Orange  
Stream: Little Shawangunk Kill  
Dates of Inspection: 10 January 1981  
9 March 1981

ASSESSMENT

Examination of available documents and a visual inspection of the dam and appurtenant structures did not reveal conditions which constitute an immediate hazard to human life or property.

Using the Corps of Engineers' screening criteria, it has been determined that the dam would be overtopped for all storms exceeding approximately 60 percent of the Probable Maximum Flood (PMF). Therefore, the spillway is adjudged "inadequate."

No signs of instability were noted in the embankment; therefore, no stability analysis will be required.

Current inspection and maintenance procedures by the owner are adequate but need to be documented. Monitoring of the reservoir levels should be expanded to include readings during peak flow periods.

The following remedial measures must be completed within one year.

Woodward Dam:

1. All low areas on the crest of the dam must be filled to the average crest elevation, compacted, and seeded.
2. Riprap must be placed on the upstream face of the dam above normal pool level.
3. The seep and wet areas at the toe of the dam must be monitored at regular intervals and during




periods of high reservoir levels for turbidity and increase in flow, which may indicate potential for the piping of embankment material.

4. The eroded areas at the downstream end of the spillway discharge channel must be repaired and protected.
5. All trees and brush must be cut off at ground level on the downstream toe, upstream slope, and spillway discharge channel. The root systems of all trees with a trunk diameter greater than 3 inches must be removed from the downstream toe of the dam. All resultant areas of erosion and cavities must be filled, graded, compacted, and seeded.
6. The animal burrow at the toe of the dam must be filled, compacted, and seeded.
7. Spalled areas in the concrete of the gate house and concrete weir must be repaired.
8. A staff gage must be installed to monitor reservoir levels above normal pool.


Greenleaf Dam:

1. The seep at the toe of the dam must be monitored at regular intervals and during periods of high reservoir levels for turbidity and increase in flow, which may indicate potential for the piping of embankment material.
2. Riprap must be placed on the upstream face of the dam above normal pool level.
3. All trees and brush must be cut off at ground level on the downstream toe of the dam. The root systems of all trees with a trunk diameter greater than 3 inches are to be removed. All resultant areas of erosion and cavities must be filled, graded, compacted, and seeded.
4. The animal burrow and depression on the downstream side of the dam must be filled, graded, compacted, and seeded.

SUBMITTED:

  
Granville Kester, Jr., P.E.  
Vice President  
MICHAEL BAKER, JR. of New York, INC.

APPROVED:

  
Colonel W.M. Smith, Jr.  
New York District Engineer

DATE:

30 JUN 1981



Overall View of Dam  
Woodward Dam  
I.D. No. NY 507  
9 March 1981

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM  
WOODWARD DAM  
I.D. No. NY 507  
DEC DAM No. 179A-562  
LOWER HUDSON RIVER BASIN  
ORANGE COUNTY, NEW YORK

SECTION 1: PROJECT INFORMATION

1.1 GENERAL

- a. Authority - The Phase I Inspection reported herein was authorized by the Department of the Army, New York District, Corps of Engineers, to fulfill the requirements of the National Dam Inspection Act, Public Law 92-367.
- b. Purpose of Inspection - This inspection was conducted to evaluate the existing conditions of the dam, to identify deficiencies and hazardous conditions, to determine if these deficiencies constitute hazards to life and property, and to recommend remedial measures where required.

1.2 DESCRIPTION OF PROJECT

- a. Description of Dam and Appurtenances - Shawangunk Lake is formed by Woodward Dam and Greenleaf Dam. Woodward Dam is an earthfill dam with a height of 29.7 feet, measured from the minimum top of dam to the toe of the dam, and a total length of 463 feet. The embankment has a crest width of 9 feet. The side slope of the upstream face is 1V:2.4H (Vertical to Horizontal) and the side slope of the downstream face is 1V:2.2H. The upstream face of the embankment is protected by riprap up to normal pool level. The original plans show a masonry core wall, but test pits dug by the owner reportedly show no evidence of this core wall. The reservoir is used as a water supply for the City of Middletown, New York.

The spillway is 50 feet from the right abutment and 18 feet upstream from the crest of the dam. The crest of the weir is 18.7 feet long (perpendicular to the direction of flow). The breadth of the weir (parallel to the direction of flow) is 1.1 feet. Flow over the spillway falls 2.7 feet to the discharge channel.

The discharge channel extends approximately 300 feet downstream from the crest of the weir. The portion of the channel extending downstream from the weir to the downstream side of the access bridge on the crest of the dam is rock-lined with stone side walls. Downstream from the access bridge, the discharge channel is a trapezoidal, rock-lined channel. A large number of trees are growing in this section of the channel.

The outlet from the reservoir consists of a 20-inch water supply line which gravity feeds to Monhegan Lake, 1 mile northeast of Shawangunk Lake. The upper level intake for the 20-inch water supply line is 11.6 feet below normal pool level, and the lower level intake is 26 feet below normal pool level. Both intake pipes (each 20-inch) are controlled by valves housed in a building on the upstream face of the dam. The plans show an 8-inch drain from the valve house to the downstream face of the dam, but this drain outlet could not be located.

Greenleaf Dam is an earthfill dam with a height of 27.9 feet, measured from the minimum top of dam to the toe of the dam, and a total length of 281 feet. The embankment has a crest width of 14.5 feet. The side slopes of the upstream and downstream faces are both 1V:2H. The upstream face of the embankment is protected by riprap up to normal pool level. Greenleaf Dam has no spillway or functioning outlet pipes.

- b. Location - Woodward Dam, on Little Shawangunk Kill, is 1 mile east of Mount Hope, New York. The reservoir and dam are in Orange County, New York. The coordinates of the dam are N 41° 27.0' and W 74° 29.7'. Woodward and Greenleaf Dams can be found on the Middletown and Otisville, New York, USGS 7.5 minute topographic quadrangles.
- c. Size Classification - The height of Woodward Dam is 29.7 feet and the reservoir storage capacity at the top of dam, elevation 769.7 feet M.S.L. (Mean Sea Level) is 1,633 acre-feet. Therefore, the dam is in the "intermediate" size category as defined by the Recommended Guidelines for Safety Inspections of Dams.

- d. Hazard Classification - Mapes Road and one home are located 3200 feet downstream from Woodward Dam. There are also three other areas downstream where the stream passes under roadways and through residential developments (see Location Plan in Appendix E). Economic damage to the roads and residential areas is likely if the dam were to fail. The possibility of excessive economic damage places Woodward Dam in the "high" hazard category as defined by the Recommended Guidelines for Safety Inspection of Dams.
- e. Ownership - The dams and reservoir are owned and operated by the City of Middletown, 16 James Street, Middletown, New York 10940. The contact person is Mr. Bill Johnson (Telephone 914-343-3169).
- f. Purpose of the Dam - The dams and reservoir are used for water supply.
- g. Design and Construction History - According to available records, the dams were originally built about 1901. The Woodward Dam was designed by W.R. Hill, consulting engineer and D.R. Lee, resident engineer. The contractor is unknown. A permit was issued to the City of Middletown to raise the dam 2.5 feet in July 1925. Plans were made for raising Woodward and Greenleaf Dams 10 feet in 1946-1947, but these plans were never implemented.
- h. Normal Operating Procedures - The Shawangunk reservoir continuously feeds Monhegan Lake through a gravity-fed 20-inch pipe. The reservoir level is normally kept at the spillway crest. The dam and spillway are visually inspected daily, and weekly records are kept on the reservoir level. The valve for the 20-inch pipe is normally open and is periodically operated to check its condition.

### 1.3 PERTINENT DATA

- a. Drainage Area (square miles) - 1.50
  - b. Discharge at Dam cubic feet per second (c.f.s.) -
- |                                 |       |
|---------------------------------|-------|
| Spillway Capacity (at Pool      |       |
| Elevation 769.7 Feet M.S.L.)* - | 532.0 |
| Reservoir Drain at Normal Pool  | 6.0   |

\*All elevations are referenced to the spillway crest, elevation 767.0 feet M.S.L., as shown on the plans supplied by the owner.

c. Elevations (Feet above M.S.L.) -

Average Top of Dam	771.7
Minimum Top of Dam	769.7
Normal Pool (Spillway Crest)	767.0
Streambed at Toe of Dam	740.0

d. Reservoir Surface Area (Acres) -

Top of Dam (Minimum)	125.4
Spillway Crest	100.7

e. Reservoir Storage Capacity (Acre-Feet) -

Top of Dam (Minimum)	1633.0
Spillway Crest	1332.0

f. Dam -

Type:	Earth
Length (Feet)	463.0
Height (Feet)	29.7
Top Width (Feet) - Design	20.0
Field	9.0
Side Slopes - Upstream - Design	1V:2H
Field	1V:2.4H
Downstream - Design	1V:2H
Field	1V:2.2H

g. Spillway -

Type:	Broad-crested concrete weir
Length of Crest Perpendicular to	
Direction of Flow (Feet)	18.7
Width of Crest Parallel to	
Direction of Flow (Feet)	1.1
Crest Elevation (Feet M.S.L.)	767.0

h. Reservoir Drain -

Type: Gravity fed 20-inch water supply line to Monhegan Lake.

Control: Manual control valves in the gate house on the crest of the dam.

The valves are normally open.

## SECTION 2: ENGINEERING DATA

### 2.1 GEOLOGY

The Woodward and Greenleaf Dams, forming Shawangunk Reservoir, are located in the southern end of the "Hudson-Mohawk Lowlands" physiographic province of New York State. Most of this province is characterized by low elevation and relief due to the erosion of outcropping weak rocks. Bedrock occurring in the immediate vicinity of the dam, as indicated on the Geologic Map of New York (J.G. Broughton and others, 1970), consists of moderately to intensely folded shales and graywacke of the Austin Glen Formation, Trenton Group (Middle Ordovician). Tabular blocks of silt shale and fine grained sandstone were noted on both abutment slopes during the visual inspection. No major faults are reported in the vicinity of the dam. This entire area has been glaciated.

### 2.2 SUBSURFACE INVESTIGATION

Original subsurface information for Woodward Dam could not be located during this inspection. However, visual observation indicates that the area appears to be covered in part by glacial debris in the form of silt and fine sand.

According to the available soils report (preliminary) for Orange County, prepared by the USDA Soil Conservation Service, local foundation and abutment materials for the dam consist of the following soils:

Left Side: Arnot Rock Outcrop Association Soils - These soils are medium textured, well drained materials formed in glacial till derived from red shale and gray sandstone. Bedrock occupies from 50 to 90 percent of the mapped areas containing these soils. Soil thickness is approximately 1 to 1-1/2 feet. Depth to seasonal high water table is approximately 2+ feet.

Right Side: Bath Silt Loam - These soils are medium textured, well drained, yellowish brown, strongly to medium acid materials with a very firm fragipan that developed in deep glacial till derived from slates, shales, and sandstone mainly. Bath soils have approximately 2 to 2-1/2



feet of moderately permeable gravelly loam over 1-1/2 to 4 feet of slowly permeable, very firm gravelly silt loam. Depth to seasonal high water table is approximately 4+ feet.

### 2.3 DAM AND APPURTENANT STRUCTURES

Woodward and Greenleaf dams are earthen embankments built around 1901 by the City of Middletown for water supply purposes. The impoundment formed, Shawangunk Reservoir, is used in conjunction with the neighboring Kinch, Monhegan, and Highland reservoirs. Plans were formulated in 1946-1947 for raising the Woodward and Greenleaf Dams to increase the storage area in Shawangunk Reservoir, but these plans were never implemented (Plate 5).

The appurtenant structures for operation of the reservoir are mainly located at Woodward Dam. A gate house on the upstream side of the dam houses two 20-inch cast iron intake pipes and the respective control valves. A 20-inch water supply pipe leads from the gate house to Monhegan Lake. An 8-inch blow-off pipe reportedly leads from the gate house to just downstream of the dam. However, the outlet of the blow-off pipe was not observed during the visual inspection (a seep was observed at the toe of the dam that is probably related to this outlet). Woodward Dam has a spillway located 50 feet to the left of the right abutment. The spillway contains a concrete weir 18.7 feet long which is offset 18 feet upstream of the crest of the dam. The crest of the weir lies 2.7 feet below the minimum embankment elevation. The discharge channel between the weir and just beyond the crest of the dam is protected by stone wing walls.

### 2.4 CONSTRUCTION RECORDS

Construction records are not available. General design plans were available for review as part of these investigations. These plans are included in Appendix E.

### 2.5 OPERATION RECORDS

Weekly observations of reservoir water levels are kept by a watchman for the City of Middletown. The watchman visually inspects Woodward Dam daily. The valves are reportedly operated periodically. Formal records of the inspections or operation of valves are not kept.

## 2.6 EVALUATION OF DATA

The background information collected during this investigation was obtained primarily from files of the New York State Department of Environmental Conservation. Supplementary information was acquired through conversations with Mr. Bill Johnson, representing the City of Middletown. The available data are considered adequate and reliable for Phase I Inspection purposes.

## SECTION 3: VISUAL INSPECTION

### 3.1 FINDINGS

- a. General - The inspection was performed on 10 January 1981. The weather was sunny and the temperature was 20° Fahrenheit. There was 4 to 6 inches of snow on the dam. The water surface was 13.6 feet below the spillway crest. This low reservoir level was attributed to an unusually low amount of precipitation occurring in the watershed prior to the inspection. Deficiencies found during the inspection will require remedial treatment. A Field Sketch of conditions found during the inspection is included in Appendix E. The complete Visual Inspection Checklist is presented as Appendix B. Because there was a snow cover on the dam during the initial inspection, a follow-up inspection was carried out on 9 March 1981.
- b. Spillway - The spillway at Woodward Dam is 50 feet from the right abutment and 18 feet upstream from the crest of the dam. The spillway is a low, broad-crested, concrete weir with masonry training walls. The masonry training walls are placed stone with many voids and extend to the downstream side of the wood deck bridge, across the discharge channel at the crest of the dam. The right masonry training wall is collapsing under the bridge. The concrete weir has relatively major spalling on the downstream face. Greenleaf Dam has no spillway.
- c. Embankment - No evidence of sloughing or subsidence was observed on the upstream or downstream slopes of the embankment at Woodward Dam.

The following is a list of deficiencies observed during the visual inspection of the embankment at Woodward Dam:

1. Minor erosion (riprap displacement) at normal pool level on the upstream face of the dam.
2. Minor low areas along the crest of the dam near the gate house.
3. A small amount of brush growing on the upstream slope of the dam.
4. Trees and brush growing on the downstream face and toe of the dam. There are six trees

24 inches in diameter and one tree 14 inches in diameter.

5. Minor seepage at the toe of the dam at Station 2+30. The estimated flow rate of the seep is 0.5 gallons per minute (g.p.m.). This could be from the 8-inch outlet pipe that could not be located during the visual inspection.

A wet area (10 square feet) was observed at Station 2+70 at the toe of the dam. The flow rate or source of this moisture could not be determined.

No evidence of sloughing or subsidence was observed on the upstream or downstream slopes of the embankment at Greenleaf Dam.

The following is a list of deficiencies observed at Greenleaf Dam during the visual inspection of the embankment:

1. Minor erosion (riprap displacement) at normal pool level on the upstream face of the dam.
  2. Trees and brush growing on the downstream face and toe of the dam. There are two trees 24 inches in diameter.
- d. 9 March 1981 Inspection - The reservoir level was approximately 4 feet higher during the second inspection than the initial inspection.

The only additional observation made at Woodward Dam was that there is an animal burrow in the downstream toe of the embankment at approximately the center of the embankment.

Several additional problems were observed at Greenleaf Dam, the dam which, along with Woodward Dam, forms Shawangunk Lake. These were: (1) an animal burrow in the downstream toe of the dam approximately 50 feet from the right abutment, (2) a wet area covering approximately 10 square feet at the downstream toe of the dam near the buried outlet for the abandoned outlet works; and (3) a small depression on the downstream face of the embankment slightly to the right of the center of the dam and approximately half-way down the downstream face. There was no measurable flow from the wet area and it could not be determined if the wet area resulted from seepage through the embankment, poor surface drainage, or seepage through the abandoned outlet works.

- e. Outlet Works - A 20-inch pipe, 19,500 feet long, runs from the reservoir at Woodward Dam to Monhegan Lake. A gate valve on the upstream side is used to control the gravity flow to Monhegan Lake. The outlet for an 8-inch drain for the gate house as shown on the original plans could not be located at the time of inspection.

The gate house is a 14-foot by 28-foot brick structure on the upstream face of Woodward Dam. Spalled areas on the gate house foundation have been recently patched, but the patches are deteriorating.

Greenleaf Dam has no operating outlet works. An abandoned valve pit is on the crest near the center of the dam.

- f. Downstream Channel - The discharge channel downstream from the Woodward Dam spillway has a mild slope with rocks, trees, and local accumulations of debris in the channel. At the downstream end of the discharge channel there is severe erosion of the channel banks.

One house and Mapes Road are located 3200 feet downstream from the dam.

- g. Reservoir - The reservoir slopes are moderate with large wooded areas. There were no signs of slope instability and sedimentation is only a minor problem. At the time of inspection, some minor sedimentation was being removed from the reservoir.

### 3.2 EVALUATION

The visual inspection of Woodward Dam revealed several deficiencies in this structure. The following items were noted:

1. Minor low areas along the crest of the dam near the gate house.
2. Minor erosion (riprap displacement) at normal pool level on the upstream face of the dam.
3. Minor seepage at the toe of the dam at Station 2+30. The estimated flow rate of the seep is 0.5 gallons per minute (g.p.m.). This could be from the 8-inch outlet pipe that could not be located during the visual inspection.

4. A wet area (10 square feet) at Station 2+70 at the toe of the dam. The flow rate or source of this moisture could not be determined.
5. Severe erosion of the channel banks exists at the downstream end of the discharge channel.
6. Trees and brush growing on the downstream face and toe of the dam. There are six trees 24 inches in diameter and one tree 14 inches in diameter.
7. Trees growing in the spillway discharge channel.
8. A small amount of brush growing on the upstream slope of the dam.
9. An animal burrow at the downstream toe of the dam at approximately the center of the embankment.
10. Spalled areas on the concrete of the gate house.

The visual inspection of Greenleaf Dam revealed several deficiencies in this structure. The following items were noted:

1. A wet area at the downstream toe of the dam near the buried outlet for the abandoned outlet works.
2. Minor erosion (riprap displacement) at normal pool level on the upstream face of the dam.
3. Trees and brush growing on the downstream face and toe of the dam. There are two trees 24 inches in diameter.
4. A small depression on the downstream face of the embankment slightly to the right of the center of the dam and approximately half-way down the downstream face.
5. An animal burrow in the downstream toe of the dam approximately 50 feet from the right abutment.

## SECTION 4: OPERATION AND MAINTENANCE PROCEDURES

### 4.1 PROCEDURES

There are no formal operating procedures. The reservoir continuously feeds Monhegan Lake through a gravity feed 20-inch pipe. The reservoir is normally kept at the spillway crest, but at the time of the inspection, the reservoir was 13.6 feet below the spillway crest because of a water shortage in the area.

### 4.2 MAINTENANCE OF THE DAM

Maintenance of Woodward Dam is the responsibility of the City of Middletown. The watchman visually inspects Woodward Dam daily and weekly records are maintained on the reservoir level. The grass is mowed and some of the trees are removed each year. The valves for the water supply line are operated periodically.

### 4.3 WARNING SYSTEM

At the time of the inspection, there was no warning system or emergency action plan in operation.

### 4.4 EVALUATION

Past maintenance of the dam and operating facilities appears to have been adequate, but, except for the water level measurements, the past activities have not been documented. A checklist should be compiled by the owner's representative to document the findings made during the periodic inspections and the maintenance items completed. A warning system and emergency action plan should be developed and put into operation.

## SECTION 5: HYDRAULIC/HYDROLOGIC DATA

### 5.1 DRAINAGE AREA CHARACTERISTICS

Delineation of the watershed of Woodward Dam was made using the USGS quadrangles for Middletown and Otisville, New York. The drainage basin consists of moderate slopes which are well covered by forests and ground vegetation. Some storage exists in Highland Lake which is upstream from Shawangunk Lake, formed by Woodward Dam and Greenleaf Dam. A small amount of residential development exists in the drainage area. The total drainage area controlled by the dam is 1.50 square miles.

### 5.2 ANALYSIS CRITERIA

A hydrologic analysis of the watershed and hydraulic analysis of dam was conducted using the U.S. Army Corps of Engineers' Flood Hydrograph Package HEC-1 DB computer program (Reference 12, Appendix D). The unit hydrograph was defined using the Snyder Unit Hydrograph Method. Estimates of Snyder hydrograph coefficients were based upon average coefficients from the Hydrologic Flood Routing Model for Lower Hudson River Basin (Reference 16, Appendix D). Precipitation data was taken from Hydrometeorological Report No. 33 (Reference 8, Appendix D). Rainfall losses were estimated at an initial loss of 1.0 inch and a constant loss rate of 0.1 inch per hour thereafter. The hydraulic capacity of the dam, reservoir, and spillway was determined by incorporating the Modified Puls Routing Method. All flood routings were begun with the reservoir at normal pool level. Outlet discharge capacity was computed by hand. The Probable Maximum Flood (PMF) and 1/2 Probable Maximum Flood (1/2 PMF) were developed and routed through the reservoir.

The runoff hydrograph was routed through Highland Lake Dam and combined with the runoff hydrograph for Shawangunk Lake, then routed through Woodward Dam.

### 5.3 SPILLWAY CAPACITY

The spillway capacity at the minimum top of dam is 532 c.f.s. There is no auxiliary or emergency spillway at Woodward Dam.

PRECEDING PAGE BLANK-NOT FILMED



#### 5.4 RESERVOIR CAPACITY

The storage capacity of Shawangunk Lake at normal pool is 1332 acre-feet. The storage capacity of the reservoir at the minimum top of dam is 1633 acre-feet. Therefore, flood control storage of the reservoir between the spillway crest and top of dam is 301 acre-feet. This volume represents a total of 1.88 inches of runoff from the watershed.

#### 5.5 FLOODS OF RECORD

No information concerning the effects of significant floods on the dam is available.

#### 5.6 OVERTOPPING POTENTIAL

The maximum capacity of the spillway is 532 c.f.s. before overtopping would occur. The peak outflows of the PMF and 1/2 PMF are 1084 c.f.s. and 422 c.f.s., respectively. Therefore, the spillway is capable of passing 60 percent of the PMF before overtopping would occur.

#### 5.7 RESERVOIR EMPTYING POTENTIAL

The reservoir can only be drawn down by the 20-inch, 19,500 foot long, gravity fed water supply line from Woodward Dam to Monhagen Lake. Neglecting inflow, the reservoir can be drawn down from normal pool in approximately 113 days. This is equivalent to an approximate drawdown rate of 0.3 feet per day, based on the hydraulic height measured from normal pool divided by the time to dewater the reservoir.

#### 5.8 EVALUATION

Woodward Dam is an "intermediate" size - "high" hazard dam requiring the spillway to pass a flood in the range of the 1/2 PMF to PMF. The PMF and 1/2 PMF were routed through the watershed and dam. It was determined that the spillway is capable of passing 60 percent of the PMF before overtopping the dam. The spillway is, therefore, judged to be "inadequate."

Conclusions pertain to present conditions and the effect of future development on the hydrology has not been considered.

## SECTION 6: STRUCTURAL STABILITY

### 6.1 EVALUATION OF EMBANKMENT STABILITY

- a. Visual Observations - No signs of potential instability were observed during the visual inspections of Woodward Dam and Greenleaf Dam. The dams are generally well maintained. A seep was observed along the downstream toe of Woodward Dam during the visual inspection; however, this is believed to be related to the 8-inch blow-off pipe outlet that is shown on available plans for the structure.
- b. Design and Construction Information - No design and construction information relating to stability is available for Woodward Dam or Greenleaf Dam.
- c. Operating Records - Woodward and Greenleaf Dams are inspected daily by a watchman for the City of Middletown. The control valves in the gate house are operated periodically.
- d. Post Construction Changes - Background information indicates that the dam may have been raised 2.5 feet in 1925. Plans were formulated in 1946-1947 for raising Woodward and Greenleaf Dams significantly to increase the storage area in Shawangunk Reservoir, but these plans were never implemented.

### 6.2 STABILITY ANALYSIS

The results of previous stability analyses, if any, were not available for Woodward Dam.

The dam appears to be a relatively homogeneous embankment composed largely of sandy silt (estimated to be ML Group Soils - Unified Classification System). The original plans for Woodward Dam indicate a masonry core wall, but test pits dug in past investigations reportedly revealed no evidence of this core wall. Woodward Dam is 29.7 feet high with a crest width of 9 feet. The upstream slope of the embankment is 1V:2.4H while the downstream slope is 1V:2.2H. The upstream slope is protected well with riprap with the exception of the top 4 to 5 feet below the crest. The dam is not subject to rapid drawdown (greater than 0.5 feet drop in the reservoir level per day) as determined by hydraulic calculations made during these investigations.

The slopes of Woodward Dam are slightly steep (particularly the upstream slope) and the crest width is narrow. However, a stability analysis is not considered necessary, based on the overall condition of the dam as observed during the visual inspection.

### 6.3 SEISMIC STABILITY

The dam is located in Seismic Zone 1 which presents no hazard from earthquakes, according to the Recommended Guidelines for Safety Inspection of Dams. This determination is contingent on the requirements that static stability conditions are satisfactory and conventional safety margins exist.

## SECTION 7: ASSESSMENT/RECOMMENDATIONS

### 7.1 ASSESSMENT

- a. Safety - Examination of available documents and visual inspections of Woodward Dam did not reveal any conditions which are considered to be hazardous.

Using the Corps of Engineers' screening criteria for review of spillway adequacy, it has been determined that the dam would be overtopped for all storms exceeding approximately 60 percent of the PMF. Therefore, the spillway is adjudged "inadequate."

- b. Adequacy of Information - The information available and the observations and measurements made during the visual inspection are considered sufficient for this Phase I Inspection Report.
- c. Need for Additional Information - No additional information is needed as a result of this Phase I Inspection Report. A stability analysis is not considered necessary at this time.
- d. Urgency - The remedial measures listed below must be completed within one year from notification.

### 7.2 RECOMMENDED MEASURES

The regular inspections and maintenance procedures presently being conducted by the owner's representative appear to be adequate, although some form of documentation is needed. A thorough checklist should be compiled by the owner's representative and completed during each inspection. Maintenance items should be completed annually. Monitoring of the reservoir level should be expanded to include reservoir levels above normal pool.

The following remedial measures must be completed within one year.

Woodward Dam:

1. All low areas on the crest of the dam must be filled to the average crest elevation, compacted, and seeded.
2. Riprap must be placed on the upstream face of the dam above normal pool level.

3. The seep and wet areas at the toe of the dam must be monitored at regular intervals and during periods of high reservoir levels for turbidity and increase in flow, which may indicate potential for the piping of embankment material.
4. The eroded areas at the downstream end of the spillway discharge channel must be repaired and protected.
5. All trees and brush must be cut off at ground level on the downstream toe, upstream slope, and spillway discharge channel. The root systems of all trees with a trunk diameter greater than 3 inches must be removed from the downstream toe of the dam. All resultant areas of erosion and cavities must be filled, graded, compacted, and seeded.
6. The animal burrow at the toe of the dam must be filled, compacted, and seeded.
7. Spalled areas in the concrete of the gate house and concrete weir must be repaired.
8. A staff gage must be installed to monitor reservoir levels above normal pool.

Greenleaf Dam:

1. The seep at the toe of the dam must be monitored at regular intervals and during periods of high reservoir levels for turbidity and increase in flow, which may indicate potential for the piping of embankment material.
2. Riprap must be placed on the upstream face of the dam above normal pool level.
3. All trees and brush must be cut off at ground level on the downstream toe of the dam. The root systems of all trees with a trunk diameter greater than 3 inches are to be removed. All resultant areas of erosion and cavities must be filled, graded, compacted, and seeded.
4. The animal burrow and depression on the downstream side of the dam must be filled, graded, compacted, and seeded.

APPENDIX A  
PHOTOGRAPHS

## CONTENTS

- Photo 1: Upstream Face of Dam from Left Abutment -  
9 March 1981
- Photo 2: Downstream Face of Dam from Right Abutment -  
9 March 1981
- Photo 3: Gate House from Reservoir Side of Dam - 9 March 1981
- Photo 4: Spillway from Upstream Side - 9 March 1981
- Photo 5: Spillway Discharge Channel with Collapsed Training  
Wall under Bridge (from Downstream Side of Bridge) -  
9 March 1981
- Photo 6: Upstream face of Greenleaf Dam from Left Abutment -  
9 March 1981

WOODWARD DAM



Photo 1. Upstream Face of Dam from Left Abutment  
9 March 1981



Photo 2. Downstream Face of Dam from Right Abutment  
9 March 1981



WOODWARD DAM



Photo 3. Gatehouse from Reservoir Side of Dam  
9 March 1981



Photo 4. Spillway from Upstream Side  
9 March 1981

WOODWARD DAM



Photo 5. Spillway Discharge Channel with Collapsed  
Training Wall under Bridge (from Downstream Side of Bridge)  
9 March 1981



Photo 6. Upstream Face of Greenleaf Dam from Left Abutment  
9 March 1981

APPENDIX B  
VISUAL INSPECTION CHECKLIST

VISUAL INSPECTION CHECKLIST

1) Basic Data

a. General

Name of Dam Woodward Dam  
Fed. I.D. # NY 507 DEC Dam No. 179A-562  
River Basin Hudson  
Location: Town Mount Hope County Orange  
Stream Name Little Shawangunk Kill  
Tributary of \_\_\_\_\_  
Latitude (N) 41°27.0' Longitude (W) 74°29.7'  
Type of Dam Earth embankment  
Hazard Category High  
Date(s) of Inspection 10 January 1981  
Weather Conditions Sunny 20°  
Reservoir Level at Time of Inspection 753.4 ft. M.S.L.

b. Inspection Personnel Wayne D. Lasch, Gary W. Todd, Rory L. Galloway

c. Persons Contacted (Including Address & Phone No.) \_\_\_\_\_  
Bill Johnson, City Hall  
16 James Street  
Middletown, NY 10940  
914/343-3169

d. History:

Date Constructed 1901 Date(s) Reconstructed 1925  
Designer W.R. Hill - Consulting Engineer  
D.R. Lee - Resident Engineer  
Constructed By Unknown  
Owner City of Middletown, NY

2) Embankment

a. Characteristics

- (1) Embankment Material Earth (sandy silt)
- (2) Cutoff Type None
- (3) Impervious Core Reported to be masonry core. However, previous test pits by owner failed to locate any masonry core.
- (4) Internal Drainage System None observed
- (5) Miscellaneous Snow covered at time of inspection, 2-6 in. on dam.

b. Crest

- (1) Vertical Alignment Minor low areas located between Sta. 2+00 and 3+00.
- (2) Horizontal Alignment Good
- (3) Surface Cracks None observed at time of inspection.
- (4) Miscellaneous Good grass cover on crest.

c. Upstream Slope

- (1) Slope (Estimate) (V:H) 1:2.4
- (2) Undesirable Growth or Debris, Animal Burrows Small amount of brush growing on slope.

- (3) Sloughing, Subsidence, or Depressions Minor erosion (riprap displacement) at normal pool level.
- (4) Slope Protection Quartzite riprap protection extending from normal pool level to water surface at time of inspection.
- (5) Surface Cracks or Movement at Toe Unobservable at time of inspection.

d. Downstream Slope

- (1) Slope (Estimate - V:H) 1:2.2
- (2) Undesirable Growth or Debris, Animal Burrows Trees (2 to 24 in. diameter) and brush along toe of dam.
- (3) Sloughing, Subsidence or Depressions None observed at time of inspection.
- (4) Surface Cracks or Movement at Toe None observed at time of inspection.
- (5) Seepage Approx. 0.5 g.p.m. at toe of dam (Sta. 2+30), wet area (approx. 10 sq. ft.) at toe of dam at Sta. 2+70.
- (6) External Drainage System (Ditches, Trenches, Blanket) None observed
- (7) Condition Around Outlet Structure None observed at time of inspection.

(8) Seepage Beyond Toe None observed

e. Abutments - Embankment Contact Appeared good at time of inspection.

(1) Erosion at Contact None observed at time of inspection.

(2) Seepage Along Contact None observed at time of inspection.

3) Drainage System

a. Description of System None

b. Condition of System None

c. Discharge from Drainage System None

4) Instrumentation (Monumentation/Surveys, Observation Wells, Weirs, Piezometers, Etc.) None observed

5) Reservoir

- a. Slopes Mild to moderate slopes, heavily wooded.
- b. Sedimentation Minor problem, sediments currently being removed to increase capacity.
- c. Unusual Conditions Which Affect Dam Highland Lake Dam upstream, 400 ft. long, 30 ft. high, 15 ft. crest width.

6) Area Downstream of Dam

- a. Downstream Hazard (No. of Homes, Highways, etc.) Mapes road and 1 home 3200 ft. downstream, economic damage only.
- b. Seepage, Unusual Growth None observed at time of inspection.
- c. Evidence of Movement Beyond Toe of Dam None observed at time of inspection.
- d. Condition of Downstream Channel Rocks, large trees and local debris in channel.

7) Spillway(s) (Including Discharge Conveyance Channel)

Spillway is located on the right upstream side of the crest.



a. General Low concrete weir with masonry training walls. Wooden bridge  
(5 ft. x 20 ft.) crosses training walls along crest of dam.

b. Condition of Service Spillway Concrete weir has relatively major  
spalling especially on the downstream face.

c. Condition of Auxiliary Spillway None

d. Condition of Discharge Conveyance Channel Masonry training walls have  
many voids. Right training wall under bridge is collapsing. Discharge  
channel has rocks, trees and local debris. Severe erosion of channel  
banks at downstream end.

8) Reservoir Drain/Outlet

Type: Pipe \_\_\_\_\_ Conduit X Other \_\_\_\_\_

Material: Concrete \_\_\_\_\_ Metal cast iron Other \_\_\_\_\_

Size: 20 in. Length 19,500 ft.

Invert Elevations: Entrance 738.0 ft.

Exit 712.0 ft. (Estimated)

Physical Condition (Describe): Unobservable X

Material: \_\_\_\_\_

Joints: \_\_\_\_\_ Alignment \_\_\_\_\_

Structural Integrity: \_\_\_\_\_

Hydraulic Capability: \_\_\_\_\_

Means of Control: Gate \_\_\_\_\_ Valve 20 in. Uncontrolled \_\_\_\_\_

Operation: Operable ☒ Inoperable \_\_\_\_\_ Other \_\_\_\_\_

Present Condition (Describe): Owner reported valves are operated  
regularly.

9) Structural - Not Applicable

a. Concrete Surfaces \_\_\_\_\_

b. Structural Cracking \_\_\_\_\_

c. Movement - Horizontal & Vertical Alignment (Settlement) \_\_\_\_\_

d. Junctions with Abutments or Embankments \_\_\_\_\_

e. Drains - Foundation, Joint, Face \_\_\_\_\_

---

---

---

f. Water Passages, Conduits, Sluices \_\_\_\_\_

---

---

---

g. Seepage or Leakage \_\_\_\_\_

---

---

---

h. Joints - Construction, etc. \_\_\_\_\_

---

---

---

i. Foundation \_\_\_\_\_

---

---

---

j. Abutments \_\_\_\_\_

---

---

---

k. Control Gates \_\_\_\_\_

---

---

---

- l. Approach & Outlet Channels \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- m. Energy Dissipators (Plunge Pool, etc.) \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- n. Intake Structures \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- o. Stability \_\_\_\_\_  
\_\_\_\_\_
- p. Miscellaneous \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

10) Appurtenant Structures (Power House, Lock, Gatehouse, Other)

- a. Description and Condition Gatehouse is a 14 ft. x 28 ft. brick structure  
located on the upstream face of the dam. Spalled areas on the gatehouse  
foundation have been recently patched but patches are deteriorating.  
\_\_\_\_\_  
\_\_\_\_\_

VISUAL INSPECTION CHECKLIST

1) Basic Data

a. General

Name of Dam Greenleaf Dam

Fed. I.D. # NY 508 DEC Dam No.

River Basin Hudson

Location: Town Mount Hope County Orange

Stream Name Little Shawangunk Kill

Tributary of

Latitude (N) 41°26.85' Longitude (W) 74°30.24'

Type of Dam Earth embankment

Hazard Category High

Date(s) of Inspection 10 January 1981

Weather Conditions Sunny 20°

Reservoir Level at Time of Inspection 753.4 ft. M.S.L.

b. Inspection Personnel Wayne D. Lasch, Gary W. Todd,

Rory L. Galloway

c. Persons Contacted (Including Address & Phone No.)

Bill Johnson, City Hall

16 James Street

Middletown, NY 10940

914/343-3169

d. History:

Date Constructed 1901 Date(s) Reconstructed 1925

Designer Unknown

Constructed By Unknown

Owner City of Middletown, NY

2) Embankment

a. Characteristics

- (1) Embankment Material Earth embankment
- (2) Cutoff Type None
- (3) Impervious Core None
- (4) Internal Drainage System None observed
- (5) Miscellaneous Snow covered at time of inspection, 2-6 in. on dam.

b. Crest

- (1) Vertical Alignment Good
- (2) Horizontal Alignment Good
- (3) Surface Cracks None observed at time of inspection.
- (4) Miscellaneous Snow covered at time of inspection.

c. Upstream Slope

- (1) Slope (Estimate) (V:H) 1:2
- (2) Undesirable Growth or Debris, Animal Burrows None observed at time of inspection.

(3) Sloughing, Subsidence, or Depressions Minor erosion (riprap displacement) at normal pool level.

(4) Slope Protection Quartzite riprap protection extending from normal pool level to water surface at time of inspection.

(5) Surface Cracks or Movement at Toe Unobservable at time of inspection.

d. Downstream Slope

(1) Slope (Estimate - V:H) 1:2

(2) Undesirable Growth or Debris, Animal Burrows Trees (2-24 in. diameter) and brush along toe of dam.

(3) Sloughing, Subsidence or Depressions None observed at time of inspection.

(4) Surface Cracks or Movement at Toe None observed at time of inspection.

(5) Seepage None observed at time of inspection.

(6) External Drainage System (Ditches, Trenches, Blanket) None

(7) Condition Around Outlet Structure None

(8) Seepage Beyond Toe None

e. Abutments - Embankment Contact Appeared good at time of inspection.

(1) Erosion at Contact None observed at time of inspection.

(2) Seepage Along Contact None observed at time of inspection.

3) Drainage System

a. Description of System None

b. Condition of System None

c. Discharge from Drainage System None

4) Instrumentation (Monumentation/Surveys, Observation Wells, Weirs, Piezometers, Etc.) None



5) Reservoir

- a. Slopes Moderate slopes, heavily wooded.
- b. Sedimentation Minor problem, sediments currently being removed to increase capacity.
- c. Unusual Conditions Which Affect Dam Highland Lake Dam upstream, 400 ft. long, 30 ft. high, 15 ft. crest width.

6) Area Downstream of Dam

- a. Downstream Hazard (No. of Homes, Highways, etc.) 1 small pond 200 ft. directly downstream, Yapes road and 1 home downstream.
- b. Seepage, Unusual Growth None observed at time of inspection.
- c. Evidence of Movement Beyond Toe of Dam None observed at time of inspection.
- d. Condition of Downstream Channel Mild slopes with trees and debris in channel.

7) Spillway(s) (Including Discharge Conveyance Channel)

None

- a. General \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- b. Condition of Service Spillway \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- c. Condition of Auxiliary Spillway \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_
- d. Condition of Discharge Conveyance Channel \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

8) Reservoir Drain/Outlet - None

Type: Pipe \_\_\_\_\_ Conduit \_\_\_\_\_ Other \_\_\_\_\_

Material: Concrete \_\_\_\_\_ Metal \_\_\_\_\_ Other \_\_\_\_\_

Size: \_\_\_\_\_ Length \_\_\_\_\_  
\_\_\_\_\_

Invert Elevations: Entrance \_\_\_\_\_

Exit \_\_\_\_\_

Physical Condition (Describe): Unobservable \_\_\_\_\_  
\_\_\_\_\_

Material: \_\_\_\_\_

Joints: \_\_\_\_\_ Alignment \_\_\_\_\_

Structural Integrity: \_\_\_\_\_

Hydraulic Capability: \_\_\_\_\_

Means of Control: Gate \_\_\_\_\_ Valve \_\_\_\_\_ Uncontrolled \_\_\_\_\_

Operation: Operable \_\_\_\_\_ Inoperable \_\_\_\_\_ Other \_\_\_\_\_

Present Condition (Describe): \_\_\_\_\_

9) Structural - Not Applicable

a. Concrete Surfaces \_\_\_\_\_

b. Structural Cracking \_\_\_\_\_

c. Movement - Horizontal & Vertical Alignment (Settlement) \_\_\_\_\_

d. Junctions with Abutments or Embankments \_\_\_\_\_

e. Drains - Foundation, Joint, Face \_\_\_\_\_

f. Water Passages, Conduits, Sluices \_\_\_\_\_

g. Seepage or Leakage \_\_\_\_\_

h. Joints - Construction, etc. \_\_\_\_\_

i. Foundation \_\_\_\_\_

j. Abutments \_\_\_\_\_

k. Control Gates \_\_\_\_\_

l. Approach & Outlet Channels \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

m. Energy Dissipators (Plunge Pool, etc.) \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_

n. Intake Structures \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

o. Stability \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_

p. Miscellaneous \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_

10) Appurtenant Structures (Power House, Lock, Gatehouse, Other)

a. Description and Condition None \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

APPENDIX C

HYDROLOGIC/HYDRAULIC DATA  
AND COMPUTATIONS

MICHAEL BAKER, JR., INC.  
THE BAKER ENGINEERS

Box 280  
Beaver, Pa. 15009

Subject WOODWARD DAM S.O. No. \_\_\_\_\_  
APPENDIX C - HYDROLOGIC/HYDRAULIC Sheet No. \_\_\_\_\_ of \_\_\_\_\_  
ENGINEERING DATA AND COMPUTATIONS Drawing No. \_\_\_\_\_  
Computed by \_\_\_\_\_ Checked by \_\_\_\_\_ Date \_\_\_\_\_

<u>SUBJECT</u>	<u>PAGE</u>
CHECK LIST FOR DAMS	1
DRAINAGE AREA AND CENTROID MAP	5
HYDROLOGIC AND HYDRAULIC DATA	6
WOODWARD DAM - TOP OF DAM PROFILE AND CROSS SECTION	7
GREENLEAF DAM - TOP OF DAM PROFILE AND CROSS SECTION	8
SPILLWAY PROFILE AND CROSS SECTION	9
SPILLWAY DISCHARGE RATING	10
20 IN. PIPE RATING	13
SPILLWAY CAPACITY ANALYSIS	14
HEC-1 COMPUTER ANALYSIS	15

CHECK LIST FOR DAMS  
HYDROLOGIC AND HYDRAULIC  
ENGINEERING DATA

AREA-CAPACITY DATA:

	<u>Elevation</u> (ft.)	<u>Surface Area</u> (acres)	<u>Storage Capacity</u> (acre-ft.)
1) Top of Dam	<u>769.7</u>	<u>125.4</u>	<u>1633</u>
2) Design High Water (Max. Design Pool)	<u>-</u>	<u>-</u>	<u>-</u>
3) Auxiliary Spillway Crest	<u>-</u>	<u>-</u>	<u>-</u>
4) Pool Level with Flashboards	<u>-</u>	<u>-</u>	<u>-</u>
5) Service Spillway Crest	<u>767.0</u>	<u>100.7</u>	<u>1332</u>

DISCHARGES

	<u>Volume</u> (cfs)
1) Average Daily	<u>Unknown</u>
2) Spillway @ Maximum High Water - Top of Dam - (El. 769.7 ft. M.S.L.)	<u>532</u>
3) Spillway @ Design High Water	<u>Unknown</u>
4) Spillway @ Auxiliary Spillway Crest Elevation	<u>-</u>
5) Low Level Outlet (20 in. C.I.P.)	<u>6</u>
6) Total (of all facilities) @ Maximum High Water	<u>538</u>
7) Maximum Known Flood	<u>Unknown</u>
8) At Time of Inspection	<u>0</u>



CREST:

ELEVATION: 769.7 ft.

Type: Earthfill dam

Width: 9 ft.

Length: 463 ft.

Spillover Low, broad-crested weir

Location 50 ft. from right abutment and 18 ft. upstream from the crest of the dam.

SPILLWAY:

SERVICE

AUXILIARY

767.0 ft.

Elevation

None

Broad-crested weir

Type

-

18.7 ft.

Width

-

Type of Control

X

Uncontrolled

-

Controlled:

-

Type

-

(Flashboards; gate)

-

Number

-

-

Size/Length

-

Invert Material

-

Anticipated Length  
of Operating Service

-

-

Chute Length

-

0.8 ft.

Height Between Spillway Crest  
& Approach Channel Invert  
(Weir Flow)

-

HYDROMETEROLOGICAL GAGES:

Type: None

Location: \_\_\_\_\_

Records:

Date: \_\_\_\_\_

Max. Reading: \_\_\_\_\_

FLOOD WATER CONTROL SYSTEM:

Warning System: None

Method of Controlled Releases (mechanisms):

A 20 in. gravity fed water supply line approximately 19,500 ft. long to

Monhagen Lake.

DRAINAGE AREA: 1.50 sq. mi.

DRAINAGE BASIN RUNOFF CHARACTERISTICS:

Land Use - Type: Wooded with light residential development.

Terrain - Relief: Moderate slopes.

Surface - Soil: Well drained.

Runoff Potential (existing or planned extensive alterations to existing surface or subsurface conditions)

There were no known plans for altering the existing runoff patterns at the time of inspection.

Potential Sedimentation problem areas (natural or man-made; present or future)

None observed at the time of inspection.

Potential Backwater problem areas for levels at maximum storage capacity including surcharge storage:

None observed at the time of inspection.

Dikes - Floodwalls (overflow & non-overflow) - Low reaches along the Reservoir perimeter:

Location: None


Elevation: \_\_\_\_\_

Reservoir:

Length @ Maximum Pool 8,500 ft. (El. 769.7 ft. M.S.L.)

Length of Shoreline (@ Spillway Crest) 20,800 ft. (3.94 mi.)

(El. 767.0 ft. M.S.L.)



QUADS: ① OTISVILLE, N.Y.  
 ② MIDDLETOWN, N.Y.

DRAINAGE AREA A = 0.72 Sq. Mi.

DRAINAGE AREA B = 0.78 Sq. Mi.

DRAINAGE AREA ABOVE  
WOODWARD DAM

SCALE: 1 IN. = 2000 FT.

MICHAEL BAKER, JR., INC.  
THE BAKER ENGINEERS

Box 280  
Beaver, Pa. 15009

Subject NEW YORK TRAIL

WOODWARD DAM

S.O. No. \_\_\_\_\_

Sheet No. 6 of 38

Drawing No. \_\_\_\_\_

Computed by WLS  
WLS

Checked by \_\_\_\_\_

Date 1/22/81

### HYDROLOGIC AND HYDRAULIC DATA

TOTAL DRAINAGE AREA ABOVE WOODWARD DAM = 10.45 SQ. MI.  
(MEASURED ON OTISVILLE AND MIDDLETOWN, N.Y. QUADS)  
= 1.50 SQ. MI.

DRAINAGE AREA BETWEEN WOODWARD DAM AND HIGHLAND  
LAKE DAM = 0.72 SQ. MI

$$T_p = C_T (L \times L_{CA})^{.3}$$

$$L = 8400 \text{ FT.} = 1.59 \text{ MI}$$

$$C_T = 2.0 \quad C_P = .63$$

$$L_{CA} = 3200 \text{ FT.} = 0.61 \text{ MI}$$

$$T_p = 2.0 [(1.59)(.61)]^{.3}$$

SURFACE AREA - ELEVATION (FROM QUAD)

$$T_p = 1.98$$

<u>ELEV.</u> <u>(FT.)</u>	<u>AREA</u> <u>(AC.)</u>
767	100.7
760	218.8

\* From Plaque @ Valve house - Capacity 434,024,999 gal. (1332.06 ACF.)

DRAINAGE AREA ABOVE HIGHLAND LAKE DAM = 0.78 SQ. MI

$$L = 6200 \text{ FT.} = 1.21 \text{ MI}$$

$$T_p = C_T (L \times L_{CA})^{.3}$$

$$C_P = 0.63 \quad C_T = 2.0$$

$$L_{CA} = 2400 \text{ FT.} = 0.45 \text{ MI}$$

$$T_p = 2.0 [(1.21)(0.45)]^{.3}$$

$$= 1.67$$

SURFACE AREA - ELEVATION (FROM QUAD)

<u>ELEV.</u> <u>(FT.)</u>	<u>AREA</u> <u>(AC.)</u>
792	117.5
800	152.4

NOTE. NORMAL POOL OF HIGHLAND LAKE  
ASSUMED TO BE AT EL. 792  
(AS SHOWN ON PLANS)


MICHAEL BAKER, JR., INC.  
THE BAKER ENGINEERS

Box 280  
Beaver, Pa. 15009


Subject WOODWARD DAM S.O. No. \_\_\_\_\_  
TOP OF DAM PROFILE AND Sheet No. 7 of 38  
TYPICAL CROSS SECTION Drawing No. \_\_\_\_\_  
Computed by GWT Checked by WLS Date 1-19-81

TOP OF DAM PROFILE (LOOKING DOWNSTREAM)

LENGTH OF DAM = 463 FT.



TYPICAL CROSS SECTION AT STATION 2+30




MICHAEL BAKER, JR., INC.  
THE BAKER ENGINEERS

Box 280  
Beaver, Pa. 15009


Subject GREENLEAF DAM S.O. No. \_\_\_\_\_  
TOP OF DAM PROFILE AND Sheet No. 8 of 38  
TYPICAL CROSS SECTION Drawing No. \_\_\_\_\_  
Computed by GLWT Checked by \_\_\_\_\_ Date 2-12-81

TOP OF DAM PROFILE (LOOKING DOWNSTREAM)

LENGTH OF DAM = 281 FT.



TYPICAL CROSS SECTION AT STATION 1+68



MICHAEL BAKER, JR., INC.  
THE BAKER ENGINEERS

Box 280  
Beaver, Pa. 15009

Subject WOODWARD DAM

S.O. No. \_\_\_\_\_

SPILLWAY PROFILE AND

Sheet No. 9 of 38

CROSS SECTION


Drawing No. \_\_\_\_\_

Computed by GWT


Checked by ULS

Date 1-19-81

SPILLWAY CROSS SECTION



SPILLWAY PROFILE





MICHAEL BAKER, JR., INC.

THE BAKER ENGINEERS

Box 280  
Beaver, Pa. 15009Subject WOODWARD DAMSPILLWAY DISCHARGE RATINGComputed by GWJChecked by WLS

S.O. No. \_\_\_\_\_

Sheet No. 10 of 38

Drawing No. \_\_\_\_\_

Date 1-20-81SPILLWAY RATINGDEVELOPE RATING CURVE BASED UPON CRITICAL FLOW OVER  
SPILLWAY:

$$V = \sqrt{gD}$$

CHOW, OPEN CHANNEL HYDRAULICS, P. 43

$$g = 32.2 \text{ FT/SEC}^2$$


$$D = \text{MEAN HYDRAULIC DEPTH} = \frac{\text{FLOW AREA}}{\text{TOP WIDTH}} = \frac{A}{T}$$

$$V = \text{MEAN FLOW VELOCITY}$$

$$Q = AV$$

SPILLWAY

ELEVATION, (FT)	FLOW DEPTH, (FT)	AREA, (FT <sup>2</sup> )	TOP WIDTH (FT)	A/T	V, FT/SEC	Q, (CFS)	V <sup>3/2g</sup>	RESERVOIR ELEV.
767.0	0'	0	18.7	0	0	0	0	777.0
767.5	.5'	9.35	18.7	0.50	4.01	37.52	.25	777.7
768.0	1.0'	18.70	18.7	1.00	5.67	106.03	.50	778.5
768.5	1.5'	28.05	18.7	1.50	6.95	194.95	.75	779.2
769.0	2.0'	37.40	18.7	2.00	8.02	300.13	1.00	780.0
769.5	2.5'	46.75	18.7	2.50	8.97	419.45	1.25	780.7

SPILLWAY DISCHARGE CURVE

MICHAEL BAKER, JR., INC.  
THE BAKER ENGINEERS

Box 280  
Beaver, Pa. 15009

Subject WOODWARD DAM S.O. No. \_\_\_\_\_  
SPILLWAY DISCHARGE RATING Sheet No. 11 of 39  
(CONTINUED) Drawing No. \_\_\_\_\_  
Computed by GWT/ALE Checked by \_\_\_\_\_ Date 1/20/81

RIGHT TRAINING WALL


ELEVATION (FT)	FLOW DEPTH (FT)	AREA (FT <sup>2</sup> )	TOPWIDTH (FT)	A/T	V (FT/SEC)	Q (CFS)	V <sup>2</sup> /2g	RESERVOIR ELEVATION
767.2	0	0	0	0	0	0	0	777.2
767.5	.3	2.10	14	.15	2.20	4.62	.07	777.57
768.0	.8	9.10	14	.65	4.57	41.63	.32	778.32
768.5	1.3	16.10	14	1.15	6.08	97.97	.57	779.07
769.0	1.8	23.10	14	1.65	7.29	168.38	.82	779.82
769.5	2.3	30.10	14	2.15	8.32	250.44	1.07	780.57



LEFT TRAINING WALL

ELEVATION (FT)	FLOW DEPTH (FT)	AREA (FT <sup>2</sup> )	TOPWIDTH (FT)	A/T	V (FT/SEC)	Q (CFS)	V <sup>2</sup> /2g	RESERVOIR ELEVATION
767.4	0	0	3.5	0	0	0	0	777.4
767.5	.1	.42	5.0	0.08	1.60	0.67	0.04	777.54
768.0	.6	4.57	9.5	0.48	3.93	17.96	0.24	778.24
768.5	1.1	9.95	12.0	0.83	5.17	51.44	0.42	778.92
769.0	1.6	16.58	14.5	1.14	6.06	100.47	0.57	779.57
769.5	2.1	24.33	16.5	1.47	6.88	167.39	0.74	780.24

SPILLWAY RATING CURVE



MICHAEL BAKER, JR., INC.  
THE BAKER ENGINEERS

Box 280  
Beaver, Pa. 15009

Subject WEDWARD DAM S.O. No. \_\_\_\_\_  
SPILLWAY DISCHARGE RATING Sheet No. 12 of 38  
SUMMARY Drawing No. \_\_\_\_\_  
Computed by GWT/HIA Checked by \_\_\_\_\_ Date 01/20/80

SPILLWAY DISCHARGE SUMMARY

ELEVATION (FT)	SPILLWAY (CFS)	RT. TRAINING WALL (CFS)	LT. TRAINING WALL (CFS)	TOTAL (CFS)
767.0	0	0	0	0
767.5	22.0	6.0	1.0	29.0
768.0	50.0	36.0	10.0	96.0
768.5	106.0	55.0	24.0	185.0
769.0	160.0	97.0	51.0	308.0
769.5	230.0	140.0	95.0	465.0
770.0	300.0	190.0	142.0	632.0

Pipe Flow

$$Q = \frac{A(2gh)^{1/2}}{[1 + K_e + K_b + K_c(L)]^{1/2}}$$

$$= \frac{2.16(2 \times 32.2 \times h)^{1/2}}{[1 + 0.78 + 0.39 + 0.0185(19,500)]^{1/2}}$$

$$= \frac{17.334 h^{1/2}}{19.0505}$$

$$= 0.9099 h^{1/2}$$

Pipe is 20" Dia Cast Iron Pipe

$$A = \pi r^2 = \pi (0.83)^2 = 2.16 \text{ ft}^2$$

$$g = 32.2 \text{ ft/sec}^2$$

$h$  = head measured from the top of  
Pipe @ outlet (est. @ 712.0 ft.)

$$L = 19,500 \text{ ft.}^*$$

$$K_e = 0.78 \quad P_g \text{ 5.5-6 SCS NEH-5}$$

$$K_b = 0.39(\text{est.})^* P_g \text{ 5.5-10 "}$$

$$K_c = 0.0185 P_g \text{ 5.5-A "}$$

$$"n" = 0.014 \text{ (uncoated Cast Iron Pipe)}$$


	Elev. (ft.)	$h$ (ft.)	$Q$ (cfs)
Invert of Drain	738	26	0
	739	27	4.73
	740	28	4.81
	742	30	4.98
	744	32	5.15
	746	34	5.31
	748	36	5.46
	750	38	5.61
	754	42	5.90
	758	46	6.17
	762	50	6.43
	766	54	6.69
Spillway Crest	767	55	6.75

\* Note: The route traveled by the drain pipe is unknown. The outlet was not located in the field. The length and outlet elevation of the pipe are estimated by knowing the approximate area of the outlet (Monhagen Lake - Normal pool elev. 712 ft.) The number and degree of bends in this pipe are unknown. One 90° bend was assumed for use in this rating curve.

MICHAEL BAKER, JR., INC.  
THE BAKER ENGINEERS

Box 280  
Beaver, Pa. 15009

Subject WOODWARD DAM S.O. No. \_\_\_\_\_  
SPILLWAY CAPACITY ANALYSIS Sheet No. 14 of 35  
Drawing No. \_\_\_\_\_  
Computed by GWT Checked by \_\_\_\_\_ Date 2-10-81







SHEET 1- OF 12



9  
 41.00A HRA.00 PERIOD LAIN EXUS LUSS  
 EAD-UF-PELUD FLON  
 COMP 4  
 AUG.00 HRA.00 PERIOD KATA EXUS LUSS  
 COMP 5  
 30.0 24.00 20.00 19.00 18.00  
 1 012.00 011.00 09.00 08.00

\*\*\*\*\*

HYDROGRAPH ROUTING

ROUTING SUBAREA A THROUGH HIGHLAND LAKE DAM

1. STAG	2. ICOMP	3. IECUN	4. IIAPE	5. JPLT	6. JPRI	7. INAME	8. ISTATE	9. IALU
1	1	0	0	0	0	1	0	0
4. LUSS	5. AVG	6. IRES	7. ISAME	8. LUPT	9. LPMP	10. LSK	11. LSK	12. LSK
0.0	0.0	1	1	0	0	0	0	0
13. STPS	14. NSTDL	15. LAG	16. AMSKK	17. X	18. ISK	19. STORA	20. ASPKAI	21. -1
1	0	0	0.0	0.0	0.0	-192.	-1	-1

STAGE	192.00	193.00	194.00	195.00	196.00	197.00	198.00	199.00	200.00
FLUW	0.0	5.00	30.00	12.00	129.00	206.00	232.00	303.00	409.00

SURFACE AREA= 0. 118. 152.

CAPACITY= 0. 392. 1468.

ELEVATION= 782. 792. 800.

1. STAG	2. ICOMP	3. IECUN	4. IIAPE	5. JPLT	6. JPRI	7. INAME	8. ISTATE	9. IALU
1	1	0	0	0	0	1	0	0

ROUTING DATA

1. STAG	2. ICOMP	3. IECUN	4. IIAPE	5. JPLT	6. JPRI	7. INAME	8. ISTATE	9. IALU
1	1	0	0	0	0	1	0	0

PEAK OUTFLOW IS 397. AT TIME 15.00 HOURS

PEAK OUTFLOW IS 213. AT TIME 16.33 HOURS

PEAK OUTFLOW IS 121. AT TIME 16.67 HOURS

PEAK OUTFLOW IS 51. AT TIME 17.00 HOURS

\*\*\*\*\*

HYDROGRAPH ROUTING

ROUTING SUBAREA A TO HIGHLAND LAKE DAM





110.0

110.0

112.0

111.8

111.6

111.4

111.3

111.0

110.0

109.1

108.4

107.5

106.6

PEAK OUTFLOW IS 108.4 AT TIME 11.41E 11.67 HOURS

PEAK OUTFLOW IS 725. AT TIME 11.41E 11.00 HOURS

PEAK OUTFLOW IS 422. AT TIME 11.41E 11.00 HOURS

PEAK OUTFLOW IS 157. AT TIME 11.41E 11.00 HOURS

\*\*\*\*\*

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO LOGARITHMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

RATIOS APPLIED TO FLOWS

OPERATION	STATION	AREA	PLAN	RATIO 1 1.00	RATIO 2 0.75	RATIO 3 0.50	RATIO 4 0.25
HYDROGRAPH AT	1	0.75 2.021	1	1057.	1392.	529.	404.
				52.5311	37.4211	26.3011	13.1511
ROUTED TO	2	0.75 2.021	1	357.	213.	121.	51.
				11.2411	6.0411	3.4111	1.4411
ROUTED TO	3	0.75 2.021	1	357.	213.	121.	51.
				11.2511	6.0411	3.4111	1.4411
HYDROGRAPH AT	4	0.72 1.801	1	1867.	1400.	933.	467.
				52.8611	39.0311	26.4311	13.2211
2 COMBINED	5	1.20 3.881	1	1987.	1481.	983.	484.
				56.2611	41.9511	27.8311	13.7111
ROUTED TO	6	1.20 3.881	1	1084.	725.	422.	157.
				30.7111	20.5211	11.9411	4.4311

# SUMMARY OF DAM SAFETY ANALYSIS

## PLAN 1 HIGHWAY LAKE DAM

ELEVATION  
STORAGE  
OUTFLOW

INITIAL VALUE  
192.00  
392.  
0.

SPILLWAY CREST  
191.00  
1032.  
200.

TOP OF DAM  
191.00  
1032.  
200.

RATIO OF PMF	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
1.00	0.20	1000.	371.	4.00	45.01	0.0
0.75	0.0	937.	213.	0.0	40.53	0.0
0.50	0.0	744.	121.	0.0	40.07	0.0
0.25	0.0	512.	51.	0.0	47.00	0.0

## PLAN 1 STATION 3

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
1.00	397.	177.1	45.01
0.75	213.	170.0	40.53
0.50	121.	176.4	40.07
0.25	51.	176.2	47.00

# SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 *WEEPWARR Dam*

RATE OF PMF	MAXIMUM RESERVOIR ELEVATION "S.S. LEVEL"	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-PI	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
1.00	770.98	1.28	1795.	1034.	9.07	43.07	6.0
0.75	770.23	0.53	1639.	725.	5.07	44.00	0.0
0.50	769.36	0.0	1592.	422.	0.0	44.00	0.0
0.25	768.34	0.0	1475.	157.	0.0	44.07	6.0

INITIAL VALUE	SPILLWAY CALCD	TOP OF DAM
767.00	767.00	769.70
1332.	1332.	1033.
0.	0.	936.

5218 3761A-277

A1 NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS  
A2 HYDROLOGIC AND HYDRAULIC ANALYSIS OF MODERN DAM  
A3 DESIGNING ANALYSIS OF AGEWARD DAM

ATIONAL PROGRAM FOR INSPECTION OF  
HYDROLOGIC AND HYDRAULIC ANALYSIS OF  
DRAINING ANALYSIS OF AGRICULTURAL DAM

900	J	0
8		1
7		1
6		1
5		1
4		1
3		1
2		1
1		1
0		1

K - J KJUFF HYDROGRAPHIC CAM  
-1 1.00

Dec 1      Dec 1

1

SHEET 25 OF 38



K		1		2		1		1	
JLWATERING - GUARDIAN LAM									
Y	KA	1	1	1	1	1	1	1	1
Y1	Y1	1	1	1	1	1	1	1	1
Y4	Y4	133.0	139.0	146.0	149.0	150.0	150.0	150.0	150.0
Y4	Y4	102.0	100.0	107.0	107.0	107.0	107.0	107.0	107.0
Y5	Y5	1	4.03	4.81	4.98	5.10	5.31	5.40	5.40
Y5	Y5	5.43	6.07	6.75	6.75	6.75	6.75	6.75	6.75
SA	SA	8.00	101.20	218.8	218.8	218.8	218.8	218.8	218.8
SE	SE	133	131	780	780	780	780	780	780
SS	SS	767.0	767.0	767.0	767.0	767.0	767.0	767.0	767.0
SD	SD	109.7	3.00	1.5	1.5	1.5	1.5	1.5	1.5
K	K	33	33	33	33	33	33	33	33

51  
52  
53  
54  
55  
56  
57  
58  
59  
60  
61  
62  
63

RUN DATE 12/11/81  
 TIME 11.10

NATIONAL PROGRAM FOR INSPECTION OF NON-FLEXURAL DAMS  
HYDROLOGIC AND HYDRAULIC ANALYSES OF SUBURBAN DAM  
GENERAL TO ANALYSIS OF MODERN DAM

JUD. SPELLEALIAN.

NO	DATE	NAME	DAY	HR	TIME	PRICE	PLT	APPL	NOTAN
400	3	0	0	0	0	0	0	0	0
			JUPER	NOI	LRUP	FRAGE	0	0	0
			5	0	0	0	0	0	0

MULTI-PLAN ANALYSES TO BE PERFORMED  
NPLAN= 1 NKIU= 1 LKIU= 1

RIID<sub>2</sub> = 1.10

姓名	性别	年龄	职业	住址	联系电话	电子邮箱	身份证号	银行卡号	支付宝账号	微信账号	其他联系方式
张三	男	35	教师	北京市海淀区中关村大街100号	13800138000	zhangsan@163.com	110101199001010001	6228480100001000100010	15888888888	zhangsan123	15888888888
李四	女	28	程序员	北京市朝阳区望京SOHO	13900139000	lisi@163.com	110105199205050002	6228480100001000100010	15888888888	lisi456	15888888888
王五	男	42	医生	上海市浦东新区世纪大道100号	13600136000	wangwu@163.com	310101195001010001	6228480100001000100010	15888888888	wangwu789	15888888888
赵六	女	30	设计师	深圳市福田区华强北路100号	13700137000	zhaoliu@163.com	440101199001010001	6228480100001000100010	15888888888	zhaoliu1011	15888888888
孙七	男	38	工程师	广州市天河区珠江新城100号	13500135000	sunqi@163.com	440101196001010001	6228480100001000100010	15888888888	sunqi1212	15888888888
周八	女	25	市场专员	深圳市南山区科技园100号	13400134000	zhouba@163.com	440101199501010001	6228480100001000100010	15888888888	zhouba1313	15888888888
吴九	男	45	销售经理	武汉市江汉区江汉路100号	13300133000	wujiu@163.com	420101195501010001	6228480100001000100010	15888888888	wujiu1414	15888888888
郑十	女	32	产品经理	成都市高新区天府大道100号	13200132000	zhengshi@163.com	510101199001010001	6228480100001000100010	15888888888	zhengshi1515	15888888888
冯十一	男	29	数据分析师	南京市鼓楼区鼓楼区100号	13100131000	fengshi1@163.com	320101199501010001	6228480100001000100010	15888888888	fengshi11616	15888888888
陈十二	女	33	运营专员	杭州市西湖区西湖区100号	13000130000	chenshi2@163.com	330101199001010001	6228480100001000100010	15888888888	chenshi21717	15888888888
林十三	男	40	项目经理	昆明市盘龙区盘龙区100号	12900129000	linshi3@163.com	530101196501010001	6228480100001000100010	15888888888	linshi31818	15888888888
周十四	女	27	客服专员	贵阳市南明区南明区100号	12800128000	zhoushi4@163.com	520101199501010001	6228480100001000100010	15888888888	zhoushi41919	15888888888
吴十五	男	36	产品经理	海口市龙华区龙华区100号	12700127000	wushi5@163.com	460101196001010001	6228480100001000100010	15888888888	wushi52020	15888888888
郑十六	女	31	市场专员	海口市秀英区秀英区100号	12600126000	zhengshi6@163.com	460101199001010001	6228480100001000100010	15888888888	zhengshi62121	15888888888
冯十七	男	41	销售经理	海口市琼山区琼山区100号	12500125000	fengshi7@163.com	460101195501010001	6228480100001000100010	15888888888	fengshi72222	15888888888
陈十八	女	26	运营专员	海口市美兰区美兰区100号	12400124000	chenshi8@163.com	460101199501010001	6228480100001000100010	15888888888	chenshi82323	15888888888
林十九	男	37	产品经理	海口市龙华区龙华区100号	12300123000	linshi9@163.com	460101196001010001	6228480100001000100010	15888888888	linshi92424	15888888888
周二十	女	28	客服专员	海口市琼山区琼山区100号	12200122000	zhoushi0@163.com	460101199501010001	6228480100001000100010	15888888888	zhoushi02525	15888888888

SUB-AREA KULTUR: COMPUTALUD.

INJUL 6JHUFF HYURUGRAPH IU JAM

[illegible]

HYDRO	ISING	TAREA	SNAPP	INSDA	TRISPL	KAT10	ISINON	ISAME	LOCAL
1	0	1-20	0-0	0-0	0-0	0-0	0	1	0
-1	0	1-20	0-0	0-0	0-0	0-0	0	1	0

[illegible]





1.03	16.00	8	04.00	0.	7.	1290.	700.0
1.04	0.0	9	12.00	0.	7.	1292.	700.0
1.04	3.00	10	80.00	0.	7.	1294.	700.0
1.04	16.00	11	80.00	0.	7.	1295.	700.5
1.05	0.0	12	90.00	0.	7.	1296.	700.5
1.05	8.00	13	10.00	0.	7.	1297.	700.5
1.05	16.00	14	112.00	0.	7.	1298.	700.4
1.06	0.0	15	120.00	0.	7.	1299.	700.3
1.06	8.00	16	120.00	0.	7.	1299.	700.3
1.06	16.00	17	136.00	0.	7.	1299.	700.2
1.07	0.0	18	144.00	0.	7.	1299.	700.2
1.07	8.00	19	152.00	0.	7.	1299.	700.1
1.07	16.00	20	160.00	0.	7.	1299.	700.1
1.08	0.0	21	168.00	0.	7.	1299.	700.1
1.08	8.00	22	176.00	0.	7.	1299.	700.0
1.08	16.00	23	184.00	0.	7.	1299.	700.0
1.09	0.0	24	192.00	0.	7.	1299.	700.5
1.09	8.00	25	200.00	0.	7.	1299.	700.5
1.09	16.00	26	208.00	0.	7.	1299.	700.5
1.10	0.0	27	216.00	0.	7.	1299.	700.5
1.10	8.00	28	224.00	0.	7.	1299.	700.5
1.10	16.00	29	232.00	0.	7.	1299.	700.5
1.11	0.0	30	240.00	0.	7.	1299.	700.5
1.11	8.00	31	248.00	0.	7.	1299.	700.5
1.11	16.00	32	256.00	0.	7.	1299.	700.5
1.12	0.0	33	264.00	0.	7.	1299.	700.5
1.12	8.00	34	272.00	0.	7.	1299.	700.5
1.12	16.00	35	280.00	0.	7.	1299.	700.5
1.13	0.0	36	288.00	0.	7.	1299.	700.5
1.13	8.00	37	296.00	0.	7.	1299.	700.5
1.13	16.00	38	304.00	0.	7.	1299.	700.5
1.14	0.0	39	312.00	0.	7.	1299.	700.5
1.14	8.00	40	320.00	0.	7.	1299.	700.5
1.14	16.00	41	328.00	0.	7.	1299.	700.5
1.15	0.0	42	336.00	0.	7.	1299.	700.5
1.15	8.00	43	344.00	0.	7.	1299.	700.5
1.15	16.00	44	352.00	0.	7.	1299.	700.5
1.16	0.0	45	360.00	0.	7.	1299.	700.5
1.16	8.00	46	368.00	0.	7.	1299.	700.5
1.16	16.00	47	376.00	0.	7.	1299.	700.5
1.17	0.0	48	384.00	0.	7.	1299.	700.5
1.17	8.00	49	392.00	0.	7.	1299.	700.5
1.17	16.00	50	400.00	0.	7.	1299.	700.5
1.18	0.0	51	408.00	0.	7.	1299.	700.5
1.18	8.00	52	416.00	0.	7.	1299.	700.5
1.18	16.00	53	424.00	0.	7.	1299.	700.5
1.19	0.0	54	432.00	0.	7.	1299.	700.5
1.19	8.00	55	440.00	0.	7.	1299.	700.5
1.19	16.00	56	448.00	0.	7.	1299.	700.5
1.20	0.0	57	456.00	0.	7.	1299.	700.5
1.20	8.00	58	464.00	0.	7.	1299.	700.5
1.20	16.00	59	472.00	0.	7.	1299.	700.5
1.21	0.0	60	480.00	0.	7.	1299.	700.5
1.21	8.00	61	488.00	0.	7.	1299.	700.5
1.21	16.00	62	496.00	0.	7.	1299.	700.5
1.22	0.0	63	504.00	0.	7.	1299.	700.5
1.22	8.00	64	512.00	0.	7.	1299.	700.5
1.22	16.00	65	520.00	0.	7.	1299.	700.5
1.23	0.0	66	528.00	0.	7.	1299.	700.5
1.23	8.00	67	536.00	0.	7.	1299.	700.5
1.23	16.00	68	544.00	0.	7.	1299.	700.5
1.24	0.0	69	552.00	0.	7.	1299.	700.5
1.24	8.00	70	560.00	0.	7.	1299.	700.5
1.24	16.00	71	568.00	0.	7.	1299.	700.5
1.25	0.0	72	576.00	0.	7.	1299.	700.5
1.25	8.00	73	584.00	0.	7.	1299.	700.5

1.25	16.00	74	552.00	U.	U.	100.0	103.2
1.26	0.0	75	600.00	U.	U.	100.0	103.4
1.26	8.00	76	608.00	U.	U.	170.	103.4
1.26	16.00	77	616.00	U.	U.	174.	103.3
1.27	0.0	78	624.00	U.	U.	109.	103.3
1.27	8.00	79	632.00	U.	U.	103.	103.2
1.27	16.00	80	640.00	U.	U.	101.	103.2
1.28	0.0	81	648.00	U.	U.	170.	103.1
1.28	8.00	82	656.00	U.	U.	112.	103.1
1.28	16.00	83	664.00	U.	U.	100.	103.0
1.29	0.0	84	672.00	U.	U.	904.	103.0
1.29	8.00	85	680.00	U.	U.	551.	102.9
1.29	16.00	86	688.00	U.	U.	922.	102.9
1.30	0.0	87	696.00	U.	U.	931.	102.8
1.30	8.00	88	704.00	U.	U.	140.	102.8
1.30	16.00	89	712.00	U.	U.	142.	102.7
1.31	0.0	90	720.00	U.	U.	130.	102.7
1.31	8.00	91	728.00	U.	U.	133.	102.6
1.31	16.00	92	736.00	U.	U.	127.	102.5
2.01	0.0	93	744.00	U.	U.	127.	102.5
2.01	8.00	94	752.00	U.	U.	124.	102.4
2.01	16.00	95	760.00	U.	U.	110.	102.4
2.02	0.0	96	768.00	U.	U.	912.	102.3
2.02	8.00	97	776.00	U.	U.	100.	102.3
2.02	16.00	98	784.00	U.	U.	904.	102.2
2.03	0.0	99	792.00	U.	U.	897.	102.2
2.03	8.00	100	800.00	U.	U.	891.	102.1
2.03	16.00	101	808.00	U.	U.	881.	102.0
2.04	0.0	102	816.00	U.	U.	882.	102.0
2.04	8.00	103	824.00	U.	U.	370.	101.9
2.05	0.0	104	832.00	U.	U.	874.	101.8
2.05	8.00	105	840.00	U.	U.	370.	101.8
2.05	16.00	106	848.00	U.	U.	802.	101.7
2.06	0.0	107	856.00	U.	U.	301.	101.7
2.06	8.00	108	864.00	U.	U.	337.	101.6
2.06	16.00	109	872.00	U.	U.	333.	101.6
2.07	0.0	110	880.00	U.	U.	840.	101.5
2.07	8.00	111	888.00	U.	U.	342.	101.5
2.07	16.00	112	896.00	U.	U.	340.	101.4
2.08	0.0	113	904.00	U.	U.	330.	101.3
2.08	8.00	114	912.00	U.	U.	314.	101.3
2.08	16.00	115	920.00	U.	U.	827.	101.2
2.09	0.0	116	928.00	U.	U.	323.	101.2
2.09	8.00	117	936.00	U.	U.	812.	101.1
2.09	16.00	118	944.00	U.	U.	810.	101.1
2.10	0.0	119	952.00	U.	U.	810.	101.0
2.10	8.00	120	960.00	U.	U.	800.	100.9
2.10	16.00	121	968.00	U.	U.	802.	100.9
2.11	0.0	122	976.00	U.	U.	170.	100.8
2.11	8.00	123	984.00	U.	U.	173.	100.8
2.11	16.00	124	992.00	U.	U.	189.	100.7
2.12	0.0	125	1000.00	U.	U.	182.	100.7
2.12	8.00	126	1008.00	U.	U.	181.	100.6
2.12	16.00	127	1016.00	U.	U.	177.	100.5
2.13	0.0	128	1024.00	U.	U.	176.	100.5
2.13	8.00	129	1032.00	U.	U.	100.	100.4
2.13	16.00	130	1040.00	U.	U.	104.	100.4
2.14	0.0	131	1048.00	U.	U.	103.	100.3
2.14	8.00	132	1056.00	U.	U.	100.	100.2
2.14	16.00	133	1064.00	U.	U.	100.	100.2
2.15	0.0	134	1072.00	U.	U.	102.	100.1
2.15	8.00	135	1080.00	U.	U.	141.	100.1
2.15	16.00	136	1088.00	U.	U.	143.	100.1
2.16	0.0	137	1096.00	U.	U.	137.	100.0
2.16	8.00	138	1104.00	U.	U.	133.	100.0

2.19	16.00	1401120.00	0.	0.	121.	159.8
2.17	0.0	1411128.00	0.	0.	122.	159.8
2.17	8.00	1421130.00	0.	0.	123.	159.7
2.17	16.00	1431144.00	0.	0.	124.	159.6
2.18	0.0	1441152.00	0.	0.	125.	159.6
2.18	8.00	1451160.00	0.	0.	126.	159.5
2.18	16.00	1461168.00	0.	0.	127.	159.4
2.19	0.0	1471176.00	0.	0.	128.	159.4
2.19	8.00	1481184.00	0.	0.	129.	159.3
2.19	16.00	1491192.00	0.	0.	130.	159.3
2.20	0.0	1501200.00	0.	0.	131.	159.2
2.20	8.00	1511208.00	0.	0.	132.	159.1
2.20	16.00	1521216.00	0.	0.	133.	159.1
2.21	0.0	1531224.00	0.	0.	134.	159.0
2.21	8.00	1541232.00	0.	0.	135.	158.9
2.21	16.00	1551240.00	0.	0.	136.	158.8
2.22	0.0	1561248.00	0.	0.	137.	158.8
2.22	8.00	1571256.00	0.	0.	138.	158.7
2.22	16.00	1581264.00	0.	0.	139.	158.6
2.23	0.0	1591272.00	0.	0.	140.	158.6
2.23	8.00	1601280.00	0.	0.	141.	158.5
2.23	16.00	1611288.00	0.	0.	142.	158.4
2.24	0.0	1621296.00	0.	0.	143.	158.4
2.24	8.00	1631304.00	0.	0.	144.	158.3
2.24	16.00	1641312.00	0.	0.	145.	158.3
2.25	0.0	1651320.00	0.	0.	146.	158.2
2.25	8.00	1661328.00	0.	0.	147.	158.2
2.25	16.00	1671336.00	0.	0.	148.	158.1
2.26	0.0	1681344.00	0.	0.	149.	158.0
2.26	8.00	1691352.00	0.	0.	150.	158.0
2.26	16.00	1701360.00	0.	0.	151.	157.9
2.27	0.0	1711368.00	0.	0.	152.	157.8
2.27	8.00	1721376.00	0.	0.	153.	157.8
2.27	16.00	1731384.00	0.	0.	154.	157.7
2.28	0.0	1741392.00	0.	0.	155.	157.6
2.28	8.00	1751400.00	0.	0.	156.	157.6
2.28	16.00	1761408.00	0.	0.	157.	157.5
2.29	0.0	1771416.00	0.	0.	158.	157.4
2.29	8.00	1781424.00	0.	0.	159.	157.4
2.29	16.00	1791432.00	0.	0.	160.	157.3
3.01	0.0	1801440.00	0.	0.	161.	157.2
3.01	8.00	1811448.00	0.	0.	162.	157.2
3.01	16.00	1821456.00	0.	0.	163.	157.1
3.02	0.0	1831464.00	0.	0.	164.	157.1
3.02	8.00	1841472.00	0.	0.	165.	157.0
3.02	16.00	1851480.00	0.	0.	166.	156.9
3.03	0.0	1861488.00	0.	0.	167.	156.8
3.03	8.00	1871496.00	0.	0.	168.	156.7
3.03	16.00	1881504.00	0.	0.	169.	156.7
3.04	0.0	1891512.00	0.	0.	170.	156.6
3.04	8.00	1901520.00	0.	0.	171.	156.6
3.04	16.00	1911528.00	0.	0.	172.	156.5
3.05	0.0	1921536.00	0.	0.	173.	156.4
3.05	8.00	1931544.00	0.	0.	174.	156.4
3.05	16.00	1941552.00	0.	0.	175.	156.3
3.06	0.0	1951560.00	0.	0.	176.	156.2
3.06	8.00	1961568.00	0.	0.	177.	156.2
3.06	16.00	1971576.00	0.	0.	178.	156.1
3.07	0.0	1981584.00	0.	0.	179.	156.1
3.07	8.00	1991592.00	0.	0.	180.	156.0
3.07	16.00	2001600.00	0.	0.	181.	155.9
3.08	0.0	2011608.00	0.	0.	182.	155.8
3.08	8.00	2021616.00	0.	0.	183.	155.8
3.08	16.00	2031624.00	0.	0.	184.	155.7
3.09	0.0	2041632.00	0.	0.	185.	155.6

3.09	16.00	2001690.00	0.	0.	100.	100.3
3.10	0.0	2011670.00	0.	0.	100.	100.2
3.10	8.00	2031600.00	0.	0.	100.	100.2
3.10	16.00	2031612.00	0.	0.	100.	100.1
3.11	0.0	2101680.00	0.	0.	100.	100.0
3.11	8.00	2111688.00	0.	0.	100.	100.0
3.11	16.00	2121690.00	0.	0.	100.	100.8
3.12	0.0	2131700.00	0.	0.	100.	100.8
3.12	8.00	2141712.00	0.	0.	100.	100.1
3.12	16.00	2151720.00	0.	0.	100.	100.0
3.13	0.0	2161728.00	0.	0.	100.	100.0
3.13	8.00	2171736.00	0.	0.	100.	100.4
3.13	16.00	2181740.00	0.	0.	100.	100.4
3.14	0.0	2191752.00	0.	0.	100.	100.3
3.14	8.00	2201760.00	0.	0.	100.	100.2
3.14	16.00	2211768.00	0.	0.	100.	100.1
3.15	0.0	2221776.00	0.	0.	100.	100.0
3.15	8.00	2231784.00	0.	0.	100.	100.5
3.15	16.00	2241792.00	0.	0.	100.	100.5
3.16	0.0	2251800.00	0.	0.	100.	100.0
3.16	8.00	2261808.00	0.	0.	100.	100.1
3.16	16.00	2271816.00	0.	0.	100.	100.0
3.17	0.0	2281824.00	0.	0.	100.	100.0
3.17	8.00	2291832.00	0.	0.	100.	100.4
3.17	16.00	2301840.00	0.	0.	100.	100.3
3.18	0.0	2311848.00	0.	0.	100.	100.3
3.18	8.00	2321856.00	0.	0.	100.	100.3
3.18	16.00	2331864.00	0.	0.	100.	100.1
3.19	0.0	2341872.00	0.	0.	100.	100.0
3.19	8.00	2351880.00	0.	0.	100.	100.5
3.19	16.00	2361888.00	0.	0.	100.	100.0
3.20	0.0	2371896.00	0.	0.	100.	100.1
3.20	8.00	2381904.00	0.	0.	100.	100.0
3.20	16.00	2391912.00	0.	0.	100.	100.0
3.21	0.0	2401920.00	0.	0.	100.	100.4
3.21	8.00	2411928.00	0.	0.	100.	100.4
3.21	16.00	2421936.00	0.	0.	100.	100.3
3.22	0.0	2431944.00	0.	0.	100.	100.2
3.22	8.00	2441952.00	0.	0.	100.	100.1
3.22	16.00	2451960.00	0.	0.	100.	100.0
3.23	0.0	2461968.00	0.	0.	100.	100.5
3.23	8.00	2471976.00	0.	0.	100.	100.0
3.23	16.00	2481984.00	0.	0.	100.	100.1
3.24	0.0	2491992.00	0.	0.	100.	100.0
3.24	8.00	2502000.00	0.	0.	100.	100.0
3.24	16.00	2512008.00	0.	0.	100.	100.4
3.25	0.0	2522016.00	0.	0.	100.	100.3
3.25	8.00	2532024.00	0.	0.	100.	100.2
3.25	16.00	2542032.00	0.	0.	100.	100.1
3.26	0.0	2552040.00	0.	0.	100.	100.0
3.26	8.00	2562048.00	0.	0.	100.	100.5
3.26	16.00	2572056.00	0.	0.	100.	100.8
3.27	0.0	2582064.00	0.	0.	100.	100.1
3.27	8.00	2592072.00	0.	0.	100.	100.0
3.27	16.00	2602080.00	0.	0.	100.	100.5
3.28	0.0	2612088.00	0.	0.	100.	100.4
3.28	8.00	2622096.00	0.	0.	100.	100.3
3.28	16.00	2632104.00	0.	0.	100.	100.2
3.29	0.0	2642112.00	0.	0.	100.	100.0
3.29	8.00	2652120.00	0.	0.	100.	100.5
3.29	16.00	2662128.00	0.	0.	100.	100.8
3.30	0.0	2672136.00	0.	0.	100.	100.1
3.30	8.00	2682144.00	0.	0.	100.	100.0
3.30	16.00	2692152.00	0.	0.	100.	100.5
3.31	0.0	2702160.00	0.	0.	100.	100.4



4.01	16.00	2122110.00	0.	0.	200.	145.1
4.01	0.0	2132104.00	0.	0.	202.	145.0
4.01	0.00	2142152.00	0.	0.	171.	140.5
4.01	16.00	2152200.00	0.	0.	175.	140.0
4.02	0.0	2162208.00	0.	0.	191.	140.1
4.02	0.00	2172210.00	0.	0.	108.	140.0
4.02	16.00	2182224.00	0.	0.	104.	140.4
4.03	0.0	2192232.00	0.	0.	100.	140.3
4.03	0.00	2202240.00	0.	0.	111.	140.2
4.03	16.00	2212248.00	0.	0.	113.	140.1
4.04	0.0	2222256.00	0.	0.	110.	141.5
4.04	0.00	2232264.00	0.	0.	100.	141.0
4.04	16.00	2242272.00	0.	0.	102.	141.1
4.05	0.0	2252280.00	0.	0.	134.	141.5
4.05	0.00	2262288.00	0.	0.	132.	141.4
4.05	16.00	2272296.00	0.	0.	132.	141.3
4.06	0.0	2282304.00	0.	0.	140.	141.1
4.06	0.00	2292312.00	0.	0.	141.	141.0
4.06	16.00	2302320.00	0.	0.	141.	140.5
4.07	0.0	2312328.00	0.	0.	131.	140.1
4.07	0.00	2322336.00	0.	0.	134.	140.0
4.07	16.00	2332344.00	0.	0.	130.	140.4
4.08	0.0	2342352.00	0.	0.	121.	140.3
4.08	0.00	2352360.00	0.	0.	123.	140.1
4.08	16.00	2362368.00	0.	0.	120.	140.0
4.09	0.0	2372376.00	0.	0.	110.	140.0
4.09	0.00	2382384.00	0.	0.	113.	140.1
4.09	16.00	2392392.00	0.	0.	109.	140.5
4.10	0.0	2402400.00	0.	0.	100.	140.4
4.10	0.00	2412408.00	0.	0.	102.	140.2
4.10	16.00	2422416.00	0.	0.	99.	140.0
4.11	0.0	2432424.00	0.	0.	95.	140.5
4.11	0.00	2442432.00	0.	0.	92.	140.1
4.11	16.00	2452440.00	0.	0.	88.	140.5
4.12	0.0	2462448.00	0.	0.	85.	140.4
4.12	0.00	2472456.00	0.	0.	82.	140.2
4.12	16.00	2482464.00	0.	0.	78.	140.0
4.13	0.0	2492472.00	0.	0.	75.	140.0
4.13	0.00	2502480.00	0.	0.	71.	140.0
4.13	16.00	2512488.00	0.	0.	68.	140.4
4.14	0.0	2522496.00	0.	0.	65.	140.2
4.14	0.00	2532504.00	0.	0.	61.	140.0
4.14	16.00	2542512.00	0.	0.	58.	140.0
4.15	0.0	2552520.00	0.	0.	55.	140.0
4.15	0.00	2562528.00	0.	0.	51.	140.4
4.15	16.00	2572536.00	0.	0.	48.	140.2
4.16	0.0	2582544.00	0.	0.	45.	140.0
4.16	0.00	2592552.00	0.	0.	41.	141.0
4.16	16.00	2602560.00	0.	0.	38.	141.5
4.17	0.0	2612568.00	0.	0.	35.	141.5
4.17	0.00	2622576.00	0.	0.	32.	141.0
4.17	16.00	2632584.00	0.	0.	28.	140.0
4.18	0.0	2642592.00	0.	0.	25.	140.5
4.18	0.00	2652600.00	0.	0.	22.	140.2
4.18	16.00	2662608.00	0.	0.	19.	140.0
4.19	0.0	2672616.00	0.	0.	10.	139.1
4.19	0.00	2682624.00	0.	0.	10.	139.4
4.19	16.00	2692632.00	0.	0.	7.	139.0
4.20	0.0	2702640.00	0.	0.	6.	130.0
4.20	0.00	2712648.00	0.	0.	4.	130.5
4.20	16.00	2722656.00	0.	0.	3.	130.4
4.21	0.0	2732664.00	0.	0.	1.	130.3
4.21	0.00	2742672.00	0.	0.	1.	130.2
4.21	16.00	2752680.00	0.	0.	1.	130.1
4.22	0.0	2762688.00	0.	0.	1.	130.1

6.22	16.00	3532704.00	U.	U.	U.	U.
6.23	0.00	3392712.00	U.	U.	U.	U.
6.23	8.00	3402720.00	U.	U.	U.	U.
6.23	16.00	3412728.00	U.	U.	U.	U.
6.24	0.00	3422736.00	U.	U.	U.	U.
6.24	8.00	3432744.00	U.	U.	U.	U.
6.24	16.00	3442752.00	U.	U.	U.	U.
6.25	0.00	3452760.00	U.	U.	U.	U.
6.25	8.00	3462768.00	U.	U.	U.	U.
6.25	16.00	3472776.00	U.	U.	U.	U.
6.26	0.00	3482784.00	U.	U.	U.	U.
6.26	8.00	3492792.00	U.	U.	U.	U.
6.26	16.00	3502800.00	U.	U.	U.	U.
6.27	0.00	3512808.00	U.	U.	U.	U.
6.27	8.00	3522816.00	U.	U.	U.	U.
6.27	16.00	3532824.00	U.	U.	U.	U.
6.28	0.00	3542832.00	U.	U.	U.	U.
6.28	8.00	3552840.00	U.	U.	U.	U.
6.28	16.00	3562848.00	U.	U.	U.	U.
6.29	0.00	3572856.00	U.	U.	U.	U.
6.29	8.00	3582864.00	U.	U.	U.	U.
6.29	16.00	3592872.00	U.	U.	U.	U.
6.30	0.00	3602880.00	U.	U.	U.	U.
6.30	8.00	3612888.00	U.	U.	U.	U.
6.30	16.00	3622896.00	U.	U.	U.	U.
6.31	0.00	3632904.00	U.	U.	U.	U.
6.31	8.00	3642912.00	U.	U.	U.	U.
6.31	16.00	3652920.00	U.	U.	U.	U.
6.32	0.00	3662928.00	U.	U.	U.	U.
6.32	8.00	3672936.00	U.	U.	U.	U.
6.32	16.00	3682944.00	U.	U.	U.	U.
6.33	0.00	3692952.00	U.	U.	U.	U.
6.33	8.00	3702960.00	U.	U.	U.	U.
6.33	16.00	3712968.00	U.	U.	U.	U.
6.34	0.00	3722976.00	U.	U.	U.	U.
6.34	8.00	3732984.00	U.	U.	U.	U.
6.34	16.00	3742992.00	U.	U.	U.	U.
6.35	0.00	3753000.00	U.	U.	U.	U.
6.35	8.00	3763008.00	U.	U.	U.	U.
6.35	16.00	3773016.00	U.	U.	U.	U.
6.36	0.00	3783024.00	U.	U.	U.	U.
6.36	8.00	3793032.00	U.	U.	U.	U.
6.36	16.00	3803040.00	U.	U.	U.	U.
6.37	0.00	3813048.00	U.	U.	U.	U.
6.37	8.00	3823056.00	U.	U.	U.	U.
6.37	16.00	3833064.00	U.	U.	U.	U.
6.38	0.00	3843072.00	U.	U.	U.	U.
6.38	8.00	3853080.00	U.	U.	U.	U.
6.38	16.00	3863088.00	U.	U.	U.	U.
6.39	0.00	3873096.00	U.	U.	U.	U.
6.39	8.00	3883104.00	U.	U.	U.	U.
6.39	16.00	3893112.00	U.	U.	U.	U.
6.40	0.00	3903120.00	U.	U.	U.	U.
6.40	8.00	3913128.00	U.	U.	U.	U.
6.40	16.00	3923136.00	U.	U.	U.	U.
6.41	0.00	3933144.00	U.	U.	U.	U.
6.41	8.00	3943152.00	U.	U.	U.	U.
6.41	16.00	3953160.00	U.	U.	U.	U.
6.42	0.00	3963168.00	U.	U.	U.	U.
6.42	8.00	3973176.00	U.	U.	U.	U.
6.42	16.00	3983184.00	U.	U.	U.	U.
6.43	0.00	3993192.00	U.	U.	U.	U.
6.43	8.00	4003200.00	U.	U.	U.	U.

PEAK	10-DAY	33-DAY	90-DAY	TOTAL VOLUME
7.	7.	7.	0.	2001.
0.	0.	0.	0.	31.
	1.00	4.92	13.97	10.37
	42.20	123.03	329.21	461.21
	133.	394.	1116.	1326.
	104.	485.	1370.	1030.

10  
MS  
INCHES

MM

AC-FT  
11133 00 M

\*\*\*\*\*

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CFS) (METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

RATIOS APPLIED TO FLOWS

OPERATION STATION ARC PLAN RATIO 1  
 1.00

HYDROGRAPH AT 1 1.00 1 0.00

ROUTE 1 2 1.00 1 0.19

PLAY I .....

PAGE 38 OF 38

APPENDIX D

REFERENCES

## REFERENCES

1. University of the State of New York, Geology of New York, Education Leaflet 20, 1966.
2. Broughton, John G. and others, "Geologic Map of New York - Lower Hudson Sheet," New York State Museum and Science Service, Map and Chart Series No. 15, 1970.
3. Dunbar, Carl O. and Waage, Karl M., Historical Geology, John Wiley and Sons, Inc., New York, 1969.
4. Soil Conservation Service, Soil Interpretations Inventory Analysis and Erosion Control - Orange County, New York, U.S. Dept. of Agriculture, January 1972.
5. Bureau of Reclamation, U.S. Dept. of the Interior, Design of Small Dams, A Water Resources Technical Publication, 1977.
6. Chow, Ven Te, Handbook of Applied Hydrology, McGraw - Hill Book Company, New York, 1964.
7. Chow, Ven Te, Open Channel Hydraulics, McGraw - Hill Book Company, New York, First Edition, 1959.
8. HMR 33, "Seasonal Variations of Probable Maximum Precipitation, East of the 105th Meridian for Areas 10 to 1000 Square Miles and Durations of 6 to 48 Hours," (1956).
9. King, Horace Williams and Brater, Ernest F., Handbook of Hydraulics, Fifth Edition, McGraw - Hill Book Company, New York, 1963.
10. Soil Conservation Service, "National Engineering Handbook - Section 4, Hydrology," U.S. Department of Agriculture, 1964.
11. Soil Conservation Service, "National Engineering Handbook - Section 5, Hydraulics," U.S. Department of Agriculture.
12. U.S. Army, Hydrological Engineering Center, "Flood Hydrograph Package (HEC-1), Dam Safety Investigations, Users Manual," Corps of Engineers, Davis, California, September 1978.
13. U.S. Army, Hydrological Engineering Center, "HEC-2 Water Surface Profiles, Users Manual," Corps of Engineers, Davis, California, October 1973.

14. U.S. Army, "Inventory of United States Dams," Corps of Engineers, 9 September 1978.
15. U.S. Army, Office of the Chief of Engineers, "Appendix D, Recommended Guidelines for Safety Inspection of Dams," National Program of Inspection of Dams, Volume 1, Corps of Engineers, Washington, D.C., May 1975.
16. George, Thomas S. and Taylor, Robert S., Hydrologic Flood Routing Model For Lower Hudson River Basin, Water Resources Engineers, Inc., 8001 Forbes Place, Suite 312, Springfield, Virginia, January 1977.
17. U.S. Army, Office of the Chief of Engineers, Engineering Circular EC-1110-2-163 (Draft Engineering Manual), "Spillway and Freeboard Requirements for Dams, Appendix C, Hydrometeorological Criteria and Hyetograph Estimates," (August 1975).
18. U.S. Army, Office of the Chief of Engineers, Engineering Circular EC-1110-2-188, "Engineering and Design, National Program of Inspection of Non-Federal Dams," Corps of Engineers, Washington, D.C., 30 December 1977.
19. U.S. Army, Office of the Chief of Engineers, Engineer Technical Letter No. ETL 1110-2-234, "Engineering and Design, National Program of Inspection of Non-Federal Dams, Review of Spillway Adequacy," Corps of Engineers, Washington, D.C., 10 May 1978.
20. U.S. Department of Commerce, "Technical Paper No. 40, Rainfall Frequency Atlas of the United States for Durations from 30 Minutes to 24 Hours and Return Periods from 1 to 100 Years," Weather Bureau, Washington, D.C., May 1961.
21. U.S. Department of Commerce, National Oceanic and Atmospheric Administration, "Hydrometeorological Report No. 51, Probable Maximum Precipitation Estimates, United States East of the 105th Meridian," Washington, D.C., June 1978.



APPENDIX E  
DRAWINGS

AD-A105 768

BAKER (MICHAEL) JR INC BEAVER PA

F/G 13/13

NATIONAL DAM SAFETY PROGRAM. WOODWARD DAM (INVENTORY NUMBER NY --ETC(U)

JUN 81 G KESTER

DACW51-81-C-0010

NL

UNCLASSIFIED

2-11-81  
41-1  
8 5 40




END  
DATE  
18 SEP 81  
DTIC


## CONTENTS

Location Plan

Watershed Map

- Plate 1a: Field Sketch of Woodward Dam
- Plate 1b: Field Sketch of Greenleaf Dam
- Plate 2: Plan of Dam (1901)
- Plate 3: Contours for Proposed Spillway
- Plate 4: Plan of Wells of Gate House and Core Wall
- Plate 5: Reconstruction Plans (1947)





MICHAEL BAKER, JR., INC.  
THE BAKER ENGINEERS

Box 280  
Beaver, Pa. 15009

Subject WOODWARD DAM S.O. No. \_\_\_\_\_  
FIELD SKETCH Sheet No. \_\_\_\_\_ of \_\_\_\_\_  
Drawing No. \_\_\_\_\_  
Computed by \_\_\_\_\_ Checked by \_\_\_\_\_ Date \_\_\_\_\_




PLATE 1a

MICHAEL BAKER, JR., INC.  
THE BAKER ENGINEERS

Box 280  
Beaver, Pa. 15009

Subject GREENLEAF DAM S.O. No. \_\_\_\_\_  
FIELD SKETCH Sheet No. \_\_\_\_\_ of \_\_\_\_\_  
Drawing No. \_\_\_\_\_  
Computed by \_\_\_\_\_ Checked by \_\_\_\_\_ Date \_\_\_\_\_






PLATE 1b



ELEVATION OF DAM.  
ON LINE "A B."

SCALE  
HOR 20' TO 1"  
VER 10' TO 1"




PLAN OF DAM.

SCALE  
20' TO 1"



IN 5 LAYERS  
WATERED  
AND  
ROLLED

**SECTION IN DETAIL  
SHOWING  
PAVING & FILLING  
SCALE  
2 TO 1**



**SECTION OF EARTH DAM  
RUBBLE MASONRY CORE  
ON LINE C.D.  
SCALE  
HORIZ. VER.  
10 TO 1"**

**WEST END.  
B**

**BOARD OF WATER COMMISSIONERS  
MIDDLETOWN  
N.Y.**


**WOODWARD DAM**


**CONSULTING ENGINEER  
JAN 1961**

**PLATE 2**



**RESIDENT ENGINEER**








- SECTION THROUGH SCREEN WELL




NOTE: THE 8 INCH AND 20 INCH PIPES ARE TO BE Laid BY THE CONTRACTOR THROUGH THE EXISTING A DISTANCE OF 80 FEET FROM THE CENTER OF THE CORE WALL.



Scale 1" = 10'

NOTES FOR  
CONSTRUCTION  
OF  
DAM



BOARD OF WATER COMMISSIONERS  
MIDDLETOWN, N. Y.

Plan of Wells and Dam and Foundation  
WOODWARD DAM

January 1911

Resident Engineer

Consulting Engineer

**-NOTE-**

ALL FOUNDATION PITS FOR STRUCTURES  
AND CORE WALLS ARE TO BE EXCAVATED TO  
FIRM BOTTOM AND NOT BE ORDERED  
ENGINEER.

NO ALLOWANCE FOR FOUNDATION  
SETTLING AND DAMPNESS OF  
MATERIALS TO BE TAKEN INTO  
ACCOUNT FOR THE DESIGN OF  
STRUCTURE BECAUSE OF ANY  
FOUNDATION




**-PLAN-**

2

742      743      744      745      746



DRAWN BY: R.V.V.  
 TRACED BY: J.M.M.  
 CHECKED BY: J.K.F.



NOTE: THIS RECONSTRUCTION WAS NEVER COMPLETED, BUT ITEMS SHOWN AS EXISTING REFLECT PRESENT CONDITIONS.

## PLATE 5

CITY OF MIDDLETOWN  
ORANGE COUNTY NEW YORK  
N.Y.S.R.W.R.W.G. SERIAL NO. 5757.

INCREASING STORAGE  
AT SHAWANGUNK LAKE

## WOODWARD DAM PLAN

SCALE 1" = 20 FEET

30 STATE ST.  
ALBANY, N.Y.

REVISED NOV. 5, 1937.

Approved: \_\_\_\_\_  
N.Y. State Dept. of Public Works

Approved: \_\_\_\_\_  
N.Y. S. Port & Public Works Planning Commission  
Chairman

NOTE: Elevation shown based on  
Bench Mark - west end of spillway  
notch - Elevation 787.01

APPENDIX F  
BACKGROUND DOCUMENTS



<input type="checkbox"/> 01	<input type="checkbox"/> 36	<input type="checkbox"/> 25	<input type="checkbox"/> 562	<input type="checkbox"/> 180474	<input type="checkbox"/> 003	<input type="checkbox"/>
RR	CITY	YR AP.	DAM NO.	IRS. DATE	USE	TYPE

AS BUILT DESCRIPTION

- |   |   |
|---|---|
| <input checked="" type="checkbox"/> Location of Sp'way and outlet | <input type="checkbox"/> Elevations                       |
| <input type="checkbox"/> Size of Sp'way and Outlet                | <input type="checkbox"/> Geometry of Non-overflow section |

GENERAL CONDITION OF NON-OVERFLOW SECTION

- |  |  |  |
|--|--|--|
| <input checked="" type="checkbox"/> Settlement       | <input checked="" type="checkbox"/> Cracks                   | <input checked="" type="checkbox"/> Deflections  |
| <input checked="" type="checkbox"/> Joints           | <input checked="" type="checkbox"/> Surface of Concrete      | <input checked="" type="checkbox"/> Leakage      |
| <input checked="" type="checkbox"/> Undermining      | <input checked="" type="checkbox"/> Settlement of Embankment | <input checked="" type="checkbox"/> Crest of Dam |
| <input checked="" type="checkbox"/> Downstream Slope | <input checked="" type="checkbox"/> Upstream Slope           | <input checked="" type="checkbox"/> Toe of Slope |

GENERAL COND. OF SP'WAY AND OUTLET WORKS

- |  |  |  |
|--|--|--|
| <input checked="" type="checkbox"/> Auxiliary Spillway   | <input checked="" type="checkbox"/> Service or Concrete Sp'way | <input checked="" type="checkbox"/> Stilling Basin |
| <input checked="" type="checkbox"/> Joints               | <input checked="" type="checkbox"/> Surface of Concrete        | <input checked="" type="checkbox"/> Spillway Toe   |
| <input checked="" type="checkbox"/> Mechanical Equipment | <input checked="" type="checkbox"/> Plunge Pool                | <input checked="" type="checkbox"/> Drain          |

- |  |  |
|--|--|
| <input type="checkbox"/> Maintenance           | <input checked="" type="checkbox"/> Hazard Class |
| <input checked="" type="checkbox"/> Evaluation | <input checked="" type="checkbox"/> 35 Inspector |

COMMENTS:

good condition

STATE OF NEW YORK  
DEPARTMENT OF  
**State Engineer and Surveyor**  
ALBANY

Received July 14 - 1925Dam No. 562 Lower Hudson WatershedDisposition Approved July 23 - 1925Serial No. 633

Foundation inspected \_\_\_\_\_

Structure inspected \_\_\_\_\_

### Application for the ~~Construction or~~ Reconstruction of a Dam

Application is hereby made to the State Engineer, Albany, N. Y., in compliance with the provisions of Chapter LXV of the Consolidated Laws and Chapter 647, Laws of 1911, Section 22 as amended, for the approval of specifications and detailed drawings, marked Westward Dam on the

Shawangunk Reservoir raising same 2 1/2 ft.  
herewith submitted for the { ~~construction~~ reconstruction } of a dam located as stated below. All provisions of law will be complied with in the erection of the proposed dam. It is intended to complete the work covered by the application about Nov 1st 1925  
(Date)

1. The dam will be on Shawangunk Reservoir flowing into \_\_\_\_\_ in the town of Mt. Hope, County of Orange and \_\_\_\_\_

-- (Give exact distance and direction from a well-known bridge, dam, village main cross-roads or mouth of a stream)

2. The name and address of the owner is City of Middletown, N.Y.

3. The dam will be used for Storage Reservoir

4. Will any part of the dam be built upon or its pond flood any State lands? No

5. The watershed at the proposed dam draining into the pond to be formed thereby is 8 square miles.

6. The proposed dam will have a pond area at the spillcrest elevation of 101 acres and will impound 20,000,000 cubic feet of water.

7. The lowest part of the natural shore of the pond is 15 feet vertically above the spillcrest, and everywhere else the shore will be at least 10-25 feet above the spillcrest.

8. The maximum known flow of the stream at the dam site was \_\_\_\_\_ cubic feet per second on \_\_\_\_\_ (Date)

9. State if any damage to life or to any buildings, roads or other property could be caused by any possible failure of the proposed dam No

10. The natural material of the bed on which the proposed dam will rest is (clay, sand, gravel, boulders, granite, shale, slate, limestone, etc.) \_\_\_\_\_

11. The material of the right bank, in the direction with the current, is.....; at the spillcrest elevation this material has a top slope of .....inches vertical to a foot horizontal on the center line of the dam, a vertical thickness at this elevation of.....feet, and the top surface extends for a vertical height of .....feet above the spillcrest.

12. The material of the left bank is.....; has a top slope of.....inches to a foot horizontal, a thickness of.....feet, and a height of.....feet.

13. State the character of the bed and the banks in respect to the hardness, perviousness, water bearing, effect of exposure to air and to water, uniformity, etc.....

14. If the bed is in layers, are the layers horizontal or inclined?..... If inclined what is the direction of the horizontal outcropping relative to the axis of the main dam and the inclination and direction of the layers in a plane perpendicular to the horizontal outcropping.....

15. What is the thickness of the layers?.....

16. Are there any porous seams or fissures?..... *No*

17. WASTES. The spillway of the above proposed dam will be..... *16* feet long in the clear; the waters will be held at the right end by a..... the top of which will be..... *6 1/2* feet above the spillcrest, and have a top width of.....feet; and at the left end by a..... the top of which will be.....feet above the spillcrest, and have a top width of.....feet.

18. There will be also for flood discharge a pipe.....inches inside diameter and the bottom will be.....feet below the spillcrest, a sluice or gate.....feet wide in the clear by.....feet high, and the bottom will be.....feet below the spillcrest.

19. APRON. Below the proposed dam there will be an apron built of.....feet long across the stream, .....feet wide and.....feet thick. The downstream side of the apron will have a thickness of.....feet for a width of.....feet.

20. PLANS. Each application for a permit of a dam over 12 feet in height must be accompanied by a location map and complete working drawings in triplicate of the proposed structure, one set of which will be returned if they are approved. Each drawing should have a title giving the parts shown, the name of the town and county in which the dam site is located, and the name of the owner and of the engineer.

The location map (U. S. Geological Quadrangle or other map) should show the exact location of the proposed dam; of buildings below the dam which might be damaged by any failure of the dam; of roads adjacent to or crossing the stream below the dam, giving the lowest elevation of the roadway above the stream bed and giving the shape,

The above information is correct to the best of my knowledge and belief.

Middletown, NY  
(Address of signer)

July 13/25  
(Date)

John M. Mearns  
Comr. Public Works  
(A person signing for owner should indicate his title or authority)

July 24, 1925.

Dam 562, L. Hudson.  
Middletown.

Commissioner of Public Works,  
Middletown,  
N. Y.

Dear Sir:

Application having been duly made to the State Engineer, you are hereby given permission up to November 30, 1925, in so far as the matter involves the jurisdiction conferred upon this office by chapter 82 of the laws of 1923, to reconstruct the Woodward dam at the northeast end of the Shawangunk Lake, designated on the records of this Department as dam No. 562, Lower Hudson watershed, by raising the embankment 2.5 ft. according to the two prints in triplicate submitted therefor, under the following conditions:

1. That the slopes of the embankment if made steeper than 1 vertical to 2-1/2 horizontal on the upstream side, be well laid in Portland cement.
2. That the spillway be laid up in cement mortar and have a cutoff of 3 ft. deep into the bed and into the banks.
3. That the Lamson dam at the southwest end of Shawangunk Lake, and designated on the records of this Department as dam No. 559, Lower Hudson watershed, be raised to the same elevation as the Woodward dam, be paved on the upstream slope and have the same depth, elevation, top width and slopes as required for the Woodward dam.
4. That the embankments and wall of the channel be constructed by paving wherever they may be subject to any wave or current erosive action.
5. That this Department be notified when the work is started.

This approval shall not be deemed to authorize any invasion of property rights, either public or private, in carrying out the above work; nor to create any claim or demand against the State of New York, nor to authorize the flooding or use of State lands; nor to acquiesce in the flooding or use of such lands.

No. 2.

Commr. Public Wks, Middletown

July 23, 1925.

On July 16th there were sent to you report blanks to be filled out, one for each of the other dams besides the Finch dam and the Lamson, Greenleaf and Woodward dams on the Shawangunk Lake, these include the two dams on Highland Lake, the two dams on Monhagen Lake and perhaps others. These report blanks were returned partially filled out for the Shawangunk Lake dams. We enclose additional blanks for the dams on Highland and Monhagen Lakes.

Acknowledgment is requested of the receipt of this letter and of the prints.

Yours very truly,

Roy G. Finch,  
State Engineer.

By  
Assistant Deputy.

ARMCK/ECH